

Uniden Engineering Services
216 John St.
P.O. Box 580
Lake City, SC 29560
Phone (843) 374-3852
Fax (843) 374-8393

Uniden

October 23, 2002


Federal Communications Commission
Authorization and Evaluation Division
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

To whom it may concern:

The undersigned, hereby attest to the fact that the FCC RF EXPOSURE INFORMATION sheet, which is being provided with this letter, will be inserted as an addendum statement to all portable marine VHF transceivers which are identified under FCC Id: AMWUT889. This attestation will remain in effect until such time that the same wording, or approved replacement language, will be prominently placed in an authorized location in the actual User's Guide. At that time, the insertion of an addendum sheet will cease.

Thank you for your consideration in this matter. Please direct all inquiries or request for further information on this subject to the undersigned.

Sincerely,

A handwritten signature in black ink, reading "James R. Haynes", is written over a horizontal line.

James R. Haynes
Vice President, Engineering and Regulatory Affairs
Uniden America Corporation

FCC RF EXPOSURE INFORMATION

WARNING! Read this information before using the VOYAGER

In August 1996 the Federal Communications Commission (FCC) of the United States with its action in Report and Order FCC 96-326 adopted an updated safety standard for human exposure to radio frequency electromagnetic energy emitted by FCC regulated transmitters. Those guidelines are consistent with the safety standard previously set by both U.S. and international standards bodies. The design of the VOYAGER complies with the FCC guidelines and these international standards.

- Never allow children to operate the radio without adult supervision and the knowledge of the following guidelines.

WARNING! It is up to the user to properly operate this radio transmitter to insure safe operation. Please adhere to the following:

Use only the supplied or an approved antenna. Unauthorized antennas, modifications, or attachments could impair call quality, damage the VOYAGER, or result in violation of FCC regulations.

Do not use the VOYAGER with a damaged antenna. If a damaged antenna comes into contact with the skin, a minor burn may result. Please contact your local dealer for a replacement antenna.

Body-worn Operation

This device was tested for typical body-worn operations using the supplied belt-clip, which typically provides a space of 1 inch from the body. To maintain compliance with FCC RF exposure requirements, Body-worn operations are restricted to the supplied belt-clip.

For hand-held operation, the radio should be held 1 inch from the user's face. The use of accessories that do not satisfy these requirements may not comply with FCC RF exposure requirements and should be avoided. For more information about RF exposure, please visit the FCC website at www.fcc.gov.

- When using an external speaker microphone, USE ONLY THE UNIDEN MODEL HHVTA07. Use of any other accessory for this purpose may invalidate your authority to operate this device.

UTZZ60889ZZ