

2.12 Transient Frequency Behavior (FCC Section 90.214)

Information regarding this requirement has been supplied by RELM Communications. Plots are provided in the following figures.



