

Helen Zhao

Subject: FW: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3MMD85A, Assessment NO.: AN05T4899, Notice#1



Exhibit-E-User_Manual_revised....
Exhibit-C-Test_Report_revised....
Exhibit-A-Block_Diagram_revise...
Exhibit-B-Internal_Photo_revis...
Exhibit-H-External_Photo_revis...
Exhibit-D-ID_Label_revised.pdf...

From: SS

Sent: Wednesday, June 29, 2005 3:56 AM

To: Helen Zhao

Subject: Re: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3MMD85A, Assessment NO.: AN05T4899, Notice#1

Dear Helen,

- #1 Please find attached the revised user manual.
- #2 This device was not used during the test. The test report is revised.
- #3 A CD containing the 1 kHz audio signal was put into the EUT and set to play mode during the test.
- #4 Please find attached block diagrams.
- #5 Please find attached the revised user manual.
- #6 Please refer to product external and internal photos.

The FCC ID label was revised and attached.

Best regards,

S. S. Liou

-----Original Message-----

From: Compliance Certification Services [mailto:helen.zhao@ccsemc.com]

Sent: Monday, June 27, 2005 4:45 PM

Subject: ACTION ELECTRONICS CO., LTD., FCC ID: ATI9R3MMD85A, Assessment NO.: AN05T4899, Notice#1

Question #1: Please revise user manual to include user information as specified in FCC 15.21.

Question #2: The test report indicates that DVD player was used during the test, however they do not show up on the setup photos. Please explain.

Question #3: The test report section 1.3 indicates that "The test signal is 1kHz standard test audio signal." However signal generator was not on the setup photos, please explain how you tested with 1KHz standard test audio signal.

Question #4: Please resubmit Block diagram for ATI9R3MMD85A, the one in the filing is for ATI9R3V0D1221. Please show antenna on the block diagram

Question #5: Please resubmit User Manual for ATI9R3MMD85A, the one in the filing is for ATI9R3V0D1221.

Question #6: Please indicate Antenna location on the Schematics.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.