

INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14010195HKG-004

Equipment Photographs

Model: 3301089

(Internal)

