



1st September 2005

TIMCO ENGINEERING INC
849 NW State Road 45
Newberry, Florida 32669

Re: Confirmation Number TC335110, Correspondence Number 22716 and 22305,
with FCC ID: AZ489FT5824.

Dear Mr. Clavier;

Motorola Inc., 8000 West Sunrise Boulevard, Fort Lauderdale, Florida, herein
submits its responses to the 10 and 26th August 2005 requests for information in
Correspondence 22716 and 22305.

RE: 22716 and 22305

Q1) Please review and update in accordance with earlier TIMCO HAC filing audits.

Q1a) Please update the filing to address all issues raised in previous TIMCO HAC
filings. Please assure that all TCB guidance is implemented during review.

Q2) Please justify use of burst average in the probe modulation factor
development with current TCB procedures. Please retest as necessary.

Response for Correspondence 22716 and 22305:

Per Motorola discussions with the FCC on Monday, 29th August 2005, and as
requested by Bruce Franca of the FCC, Motorola has retested all the models exactly
as specified in C63.19-2005 Annex C.3.1, rd. 3.4 and the Office of Engineering. A
new report is provided accordingly for each model. The results for all the re-tested
models achieve the same M rating (M3 or better).

Contact me at (954) 723-5793 if you require any additional information.

Sincerely,

/s/ Mike Ramnath (signed)

Manager, Regulatory Compliance

Email: Mike.Ramnath@motorola.com