


Boomer-II 800MHz OEM Modem Internal Photos

With shields on



With shields removed

