

**Exhibit 7B MPE Test Report Photographs****Motorola Solutions Inc.****EME Test Laboratory**

Motorola Solutions Malaysia Sdn Bhd (Innoplex)
Plot 2A, Medan Bayan Lepas,
Mukim 12 SWD 11900 Bayan Lepas Penang, Malaysia.



Radio and Control Head

Tiong

Tiong Nguk Ing
Deputy Technical Manager
Approval Date: 11/1/2016

**Tiong
Nguk
Ing**

Digitally signed by
Tiong Nguk Ing
DN: cn=Tiong Nguk Ing,
o=Motorola Solutions,
ou=Regulatory
Compliance Lab,
email=n.i.tiong@motoro
lasolutions.com, c=MY
Date: 2016.11.01
15:28:33 +08'00'

Document Revision History

Date	Revision	Comments
11/1/2016	A	Initial release

1.0 Antenna Photograph(s)



VHF Antenna kit numbers, from left to right;
AN000197A01 (HAD4023A), AN000197A02 (HAD4024A), AN000197A03 (HAD4025A) and
AN000197A04 (HAD4026A)



UHF Antenna kit numbers, from left to right;
AN000197A05 (HAE6014A), AN000197A06 (HAE6032A), AN000197A07 (HAE6033A),
AN000197A08 (HAE6034A) and AN000197A09 (HAD4026A)



**7/800 Antenna kit numbers, from left to right;
AN000197A10 (HAF4015A) and AN000197A11 (HAF4018A)**

2.0 Test Measurement Setup Photos



Test measurement setup for Bystander



Test measurement setup for Operator