

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Shonan EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)

UL Japan, Inc.

Shonan EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Pre-Check Worst Case Position


**Module
X-axis**



Y-axis




Z-axis




**Antenna
Serial number 1
X-axis**




Y-axis




Z-axis




**Antenna
Serial number 4
X-axis**



Y-axis



Z-axis



End of Report