

Interactive Technologies Inc

EXHIBIT A
ID Label / Location



**Household Fire and Burglary
Warning System Control Unit**

S4006

ISSUE NO: AE6497

01/30/02

Model: 60-879

Input: 3.6VDC

Board Number: 57-786

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code ANSI/NFPA 72-1993 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02669) INTERNAL BATTERY: 3.6VDC The battery is automatically tested every 4 hours. REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT ONLY: Saft LS 14500C Wiring Diagram: See installation Manual 466-1849. This system is intended to be checked by a qualified technician at least every three years.

This device complies with FCC rules Part 15. Operation is subject to the following two conditions:
1) this device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesired operation.

Complies with Part 68 FCC Rules
FCC Reg. No. B42AL01B46059
Ringer Equivalence 0.3B (AC)
Load Number 0,1

FCC ID: B4Z-786A-DTIM
Canada IC: 867A 12000

Interactive Technologies Inc.
2266 North 2nd Street
North St. Paul, MN 55104

WARNING:

**DISCONNECT TELCO BEFORE SERVICING.
CAUTION: IMPROPER CONNECTIONS MAY
RESULT IN DAMAGE TO THE EQUIPMENT.**

US Patents xxxxxxxxx and others pending

42-248-xx

02/11/02 7:53 AM

FCC ID: B4Z-786A-DTIM

C:\WINNT\Profiles\Kenl.Nelson\Desktop\FCC Documintation\Submittles\DTIM\peices\id_label.DOC