

Model: 60-879

Input: 3.6VDC

Board Number: 57-786

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code ANSI/NFPA 72-1993 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02669) **INTERNAL BATTERY: 3.6VDC** The battery is automatically tested every 4 hours. **REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT ONLY: Saft LS 14500C** Wiring Diagram: See installation Manual 466-1849. This system is intended to be checked by a qualified technician at least every three years.

This device complies with FCC rules Part 15. Operation is subject to the following two conditions:
1) this device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesired operation.

Complies with Part 68 FCC Rules
FCC Reg. No. B42AL01B46059
Ringer Equivalence 0.3B (AC)
Load Number 0.1

FCC ID: B4Z-786A-DTIM
Canada IC: 867A 12000

WARNING:

**DISCONNECT TELCO BEFORE SERVICING.
CAUTION: IMPROPER CONNECTIONS MAY
RESULT IN DAMAGE TO THE EQUIPMENT.**

US Patents 4,855,713, 4,864,636 and others pending

42-248-46 Rev A

GE Interlogix Inc.
2266 North 2nd Street
North St. Paul, MN 55104