









警告 WARNING

送信機のチャネル変更は、無線チャネルの管理者(結核管理者)の責任下において行ってください。誤った運用は、患者を取り違えるなどの重大な事故を引き起こすおそれがあります。結核管理者は必ず以下のことを行ってください。


- 施設内で使用しているすべてのチャネルを把握し、チャネル変更による混信などの発生を防止してください。
- チャネル変更後、受信モニタで変更後のチャネルで確実に受信できることを確認してください。
- チャネル変更をする場合は、送信機のチャネル銘板を貼り替えてください。また、必要に応じてゾーンラベルも貼り替えてください。

The following action must be taken to properly receive the transmitter signal of the correct patient on the receiving instrument. Otherwise, there may be signal loss or signals may mix causing a serious accident, such as monitoring a different patient.

- Assign a channel administrator in the hospital and only he or she should manage channel assignment on his or her responsibility.
- The channel administrator must manage the channels in the facility so that there is no signal interference.
- When the transmitter channel is changed, the channel administrator must check that the channel on the receiving monitor is also changed and the signal is properly received.
- The channel administrator must replace the channel number label on the transmitter with the new one after changing the channel.

 NIHON KOHDEN

POWER



SERIAL



...EL WRITER



TRANSMITTER

MODEL ZM-940PA

[EN] 90001

--- 3.6V

[EN] 2005



ZM-940PA
90001 AA

Made in Japan
NIHON KOHDEN CORPORATION
1-31-4, Matsubara, Shizuoka, Tokyo, Japan

FCC ID B6B ZM-940PA

Operation of this equipment requires the prior coordination with
a frequency coordinator designated by the FCC for the Wireless
Medical Telemetry Service.