



HP Inc.
1501 Page Mill Road, Palo
Alto, CA 94303-1112 USA
www.hp.com

Federal Communications Commission
7435 Oakland Mills Road
Columbia, Maryland 21046
USA

Date: January 7, 2020

Re: Change of Identification Authorization, FCC ID: TX2-RTL8822CE

To Whom It May Concern:

The purpose of this letter is to apply for a change in identification as specified under 47CFR2.933 of the FCC rules, based on the original FCC ID: TX2-RTL8822CE, grant date: 11/02/2018.

1. The equipment bearing the modified FCC ID: B94-RTL8822CED is electrically identical to original equipment, there is no change in design, circuitry or construction.
2. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
3. The original software security exhibit showing this device meets the requirements of KDB 594280 continue to be representative of and applicable to the equipment bearing the changed identification.
4. As new grantee, we, **HP Inc.**, responsible for changes to the device and will not alter or offer any capabilities that will modify DFS settings.
5. Grant line entry reduction: Requesting grant line entries be reduced, all frequencies are the same as the original grant, just reduced in accordance with KDB634817.

Sincerely,

A handwritten signature in black ink that reads 'Jim Chang'.

Printed Name / Title: Jim Chang/Manager
Company: SGS Taiwan Ltd.