

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All cables are removed prior to testing.



Test Position Top 0 mm Gap

Note: All cables are removed prior to testing.



Test Position Right 0 mm Gap



Test Position Back with Brown Keyboard Case

Note: All cables are removed prior to testing.



Test Position Back with Gray Case

Note: All cables are removed prior to testing.



Test Position Back with Gray Case in Laptop Mode


Note: All cables are removed prior to testing.



Front of Device Tablet Mode



Back of Device Tablet Mode



Laptop Mode Gray Case Configuration #1



Laptop Mode Gray Case Configuration #2



Laptop Mode Brown Case Configuration #1



Laptop Mode Brown Case Configuration #2