

3390 East Harmony Road
Fort Collins
Colorado 80528
United States



To whom it may concern:

This device with FCC ID: [B94HNI66C4SPY](#) integrates a 5G WWAN module:

	FCC ID	Equipment Class	Date of Grant	Rule Part
5G WWAN module	2AQ68T99W640	PCS	09/03/2024	22/24/27/90
5G WWAN module	2AQ68T99W640	CBE	09/03/2024	96

, which was applied under a changed FCC ID from **FCC ID: J9C-M2X72** (Grant Date: **08/14/2024**). No hardware design changes are made on the module, and the software has not been changed to increase the RF output power of the module and provided host level antenna gain is less than the original module grant. Pursuant to KDB 996369 D02, the original modular report (Report Number details see below) are submitted to represent the compliance of Part 2/22/24/27/90 conducted/radiated testing items of this device. Worst radiated cases found in module level testing are performed on the host level to ensure the compliance is kept.

Modular Test Report Number	
FG3D2803-02A	FG3D2803-02E
FG3D2803-02B	FG3D2803-02F
FG3D2803-02C	FG3D2803-02G
FG3D2803-02D	


Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T : +886 2 3789-2469