

Request for Class II Permissive Change

May 22, 2024

UL Verification Services Inc.
47173 Benicia Street, Fremont, CA 94538FCC ID : BABTN0023A
Applicant : DENSO TEN Limited

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: BABTN0023A granted on 10/28/2021.
We changed the following points from the original model.

- Exterior Design
- Addition of Indicator Board
- SW PCB Change
- CPU PCB Change (GPS improvement)
- Antenna cable


We submit the following documents related to this change. There is no change before and after change except for these documents.

☒	Test Report
☒	RF Exposure
☒	External Photo
☒	Internal Photo
☐	User Manual
☐	Label Drawing/ Location
☐	Block Diagram
☒	Theory of Operation
☒	Schematic Diagram
☐	Parts List
☐	Tune up Info.

This time, we performed the testing and confirmed that this product still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely,



Kaoru Abe
Department General Manager
Quality Assurance Group Quality Planning Div
Regulatory Management Dept.
DENSO TEN Limited