16QAM, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.3. LTE BAND 5 BANDEDGE

QPSK, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.4. LTE BAND 7 ADJACENT CHANNEL POWER

QPSK, (5.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-24



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (5.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-24



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (10.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB1-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-49



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



LOW CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-49



HIGH CH, RB50-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (15.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB75-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-74



HIGH CH, RB75-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (15.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB75-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-74



HIGH CH, RB75-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (20.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB100-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-99



HIGH CH, RB100-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (20.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB100-0



HIGH CH, RB1-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-99



HIGH CH, RB100-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.5. LTE BAND 12 BANDEDGE

QPSK, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.6. LTE BAND 13 ADJACENT CHANNEL POWER

QPSK, (5.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-24



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (5.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

HIGH CH, RB1-24



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (10.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

MID CH, RB50-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (10.0 MHz BAND WIDTH)





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

MID CH, RB50-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.7. LTE BAND 17 BANDEDGE

QPSK, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB25-0



HIGH CH, RB25-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (10.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-49



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB50-0



HIGH CH, RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.8. LTE BAND 25 BANDEDGE

QPSK, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (1.4 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-5



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB6-0



HIGH CH, RB6-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

16QAM, (3.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-14



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LOW CH, RB15-0



HIGH CH, RB15-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

QPSK, (5.0 MHz BAND WIDTH)

LOW CH, RB1-0



HIGH CH, RB1-24



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.