

LTE B41 20MHz QPSK High Channel RB1-0



LTE B41 20MHz 16QAM High Channel RB1-0



LTE B41 20MHz QPSK High Channel RB1-99



LTE B41 20MHz 16QAM High Channel RB1-99



LTE B41 20MHz QPSK High Channel RB100-0



LTE B41 20MHz 16QAM High Channel RB100-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.12. LTE BAND 66 BANDEDGE



LTE B66 1.4MHz QPSK Low Channel RB1-0



LTE B66 1.4MHz QPSK High Channel RB1-5



LTE B66 1.4MHz QPSK Low Channel RB6-0



LTE B66 1.4MHz QPSK High Channel RB6-0



LTE B66 1.4MHz 16QAM Low Channel RB1-0



LTE B66 1.4MHz 16QAM High Channel RB1-5

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 1.4MHz 16QAM Low Channel RB6-0



LTE B66 1.4MHz 16QAM High Channel RB6-0



LTE B66 3MHz QPSK Low Channel RB1-0



LTE B66 3MHz QPSK High Channel RB1-14



LTE B66 3MHz QPSK Low Channel RB15-0



LTE B66 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 3MHz 16QAM Low Channel RB1-0



LTE B66 3MHz 16QAM High Channel RB1-14



LTE B66 3MHz 16QAM Low Channel RB15-0



LTE B66 3MHz 16QAM High Channel RB15-0



LTE B66 5MHz QPSK Low Channel RB1-0



LTE B66 5MHz QPSK High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 5MHz QPSK Low Channel RB25-0



LTE B66 5MHz QPSK High Channel RB25-0



LTE B66 5MHz 16QAM Low Channel RB1-0



LTE B66 5MHz 16QAM High Channel RB1-24



LTE B66 5MHz 16QAM Low Channel RB25-0



LTE B66 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 10MHz QPSK Low Channel RB1-0



LTE B66 10MHz QPSK High Channel RB1-49



LTE B66 10MHz QPSK Low Channel RB50-0



LTE B66 10MHz QPSK High Channel RB50-0



LTE B66 10MHz 16QAM Low Channel RB1-0



LTE B66 10MHz 16QAM High Channel RB1-49

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 10MHz 16QAM Low Channel RB50-0



LTE B66 10MHz 16QAM High Channel RB50-0



LTE B66 15MHz QPSK Low Channel RB1-0



LTE B66 15MHz QPSK High Channel RB1-74



LTE B66 15MHz QPSK Low Channel RB75-0



LTE B66 15MHz QPSK High Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 15MHz 16QAM Low Channel RB1-0



LTE B66 15MHz 16QAM High Channel RB1-74



LTE B66 15MHz 16QAM Low Channel RB75-0



LTE B66 15MHz 16QAM High Channel RB75-0



LTE B66 20MHz QPSK Low Channel RB1-0



LTE B66 20MHz QPSK High Channel RB1-99

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 20MHz QPSK Low Channel RB100-0



LTE B66 20MHz QPSK High Channel RB100-0



LTE B66 20MHz 16QAM Low Channel RB1-0



LTE B66 20MHz 16QAM High Channel RB1-99



LTE B66 20MHz 16QAM Low Channel RB100-0



LTE B66 20MHz 16QAM High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3. OUT OF BAND EMISSIONS

RULE PART(S)

§2.1051, §22.901, §22.917, §24.238, §27.53, §90.691 and §90.543

LIMITS

FCC: §22.917, §24.238, §27.53 (c), (g), (h), §90.691, 90.543 (Band 14)
The minimum permissible attenuation level of any spurious emissions is 43 + 10 log (P) dB where transmitting power (P) in Watts.

FCC: §27.53 (a) (Band 30)§
The minimum permissible attenuation level of any spurious emissions is 70 + 10 log (P) dB where transmitting power (P) in Watts.

FCC: §27.53 (m) (Band 7, 41)
The minimum permissible attenuation level of any spurious emissions is 55 + 10 log (P) dB where transmitting power (P) in Watts.

TEST PROCEDURE

The RF output of the transmitter was connected to a spectrum analyzer through a calibrated coaxial cable. Sufficient scans were taken to show the out-of-band Emissions, if any, up to 10th harmonic. Multiple sweeps were recorded in maximum hold mode using a peak detector to ensure that the worst-case emissions were caught.

For each out of band emissions measurement:

- Set display line at -13 dBm, -25dBm and -40dBm according to the band Limit
- Set RBW & VBW to 100 kHz for the measurement below 1 GHz, and 1 MHz for the measurement above 1 GHz. (NOTE: Worst case set RBW/VBW to 1MHz/3MHz)

MODES TESTED

- LTE Band 2
- LTE Band 5
- LTE Band 7
- LTE Band 12
- LTE Band 13
- LTE Band 14
- LTE Band 17
- LTE Band 25
- LTE Band 26
- LTE Band 30
- LTE Band 41
- LTE Band 66

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.1. ANT 1, LTE BAND 2



LTE B2 1.4MHz QPSK Low Channel RB1-0



LTE B2 1.4MHz 16QAM Low Channel RB1-0



LTE B2 1.4MHz QPSK Middle Channel RB1-0



LTE B2 1.4MHz 16QAM Middle Channel RB1-0



LTE B2 1.4MHz QPSK High Channel RB1-0



LTE B2 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 3MHz QPSK Low Channel RB1-0



LTE B2 3MHz 16QAM Low Channel RB1-0



LTE B2 3MHz QPSK Middle Channel RB1-0



LTE B2 3MHz 16QAM Middle Channel RB1-0



LTE B2 3MHz QPSK High Channel RB1-0



LTE B2 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 5MHz QPSK Low Channel RB1-0



LTE B2 5MHz 16QAM Low Channel RB1-0



LTE B2 5MHz QPSK Middle Channel RB1-0



LTE B2 5MHz 16QAM Middle Channel RB1-0



LTE B2 5MHz QPSK High Channel RB1-0



LTE B2 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 10MHz QPSK Low Channel RB1-0



LTE B2 10MHz 16QAM Low Channel RB1-0



LTE B2 10MHz QPSK Middle Channel RB1-0



LTE B2 10MHz 16QAM Middle Channel RB1-0



LTE B2 10MHz QPSK High Channel RB1-0



LTE B2 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 15MHz QPSK Low Channel RB1-0



LTE B2 15MHz 16QAM Low Channel RB1-0



LTE B2 15MHz QPSK Middle Channel RB1-0



LTE B2 15MHz 16QAM Middle Channel RB1-0



LTE B2 15MHz QPSK High Channel RB1-0



LTE B2 15MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 20MHz QPSK Low Channel RB1-0



LTE B2 20MHz 16QAM Low Channel RB1-0



LTE B2 20MHz QPSK Middle Channel RB1-0



LTE B2 20MHz 16QAM Middle Channel RB1-0



LTE B2 20MHz QPSK High Channel RB1-0



LTE B2 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.2. ANT 1, LTE BAND 5



LTE B5 1.4MHz QPSK Low Channel RB1-0



LTE B5 1.4MHz 16QAM Low Channel RB1-0



LTE B5 1.4MHz QPSK Middle Channel RB1-0



LTE B5 1.4MHz 16QAM Middle Channel RB1-0



LTE B5 1.4MHz QPSK High Channel RB1-0



LTE B5 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 3MHz QPSK Low Channel RB1-0



LTE B5 3MHz 16QAM Low Channel RB1-0



LTE B5 3MHz QPSK Middle Channel RB1-0



LTE B5 3MHz 16QAM Middle Channel RB1-0



LTE B5 3MHz QPSK High Channel RB1-0



LTE B5 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 5MHz QPSK Low Channel RB1-0



LTE B5 5MHz 16QAM Low Channel RB1-0



LTE B5 5MHz QPSK Middle Channel RB1-0



LTE B5 5MHz 16QAM Middle Channel RB1-0



LTE B5 5MHz QPSK High Channel RB1-0



LTE B5 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 10MHz QPSK Low Channel RB1-0



LTE B5 10MHz 16QAM Low Channel RB1-0



LTE B5 10MHz QPSK Middle Channel RB1-0



LTE B5 10MHz 16QAM Middle Channel RB1-0



LTE B5 10MHz QPSK High Channel RB1-0



LTE B5 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.3. ANT 1, LTE BAND 7



LTE B7 5MHz QPSK Low Channel RB1-0



LTE B7 5MHz 16QAM Low Channel RB1-0



LTE B7 5MHz QPSK Middle Channel RB1-0



LTE B7 5MHz 16QAM Middle Channel RB1-0



LTE B7 5MHz QPSK High Channel RB1-0



LTE B7 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 10MHz QPSK Low Channel RB1-0



LTE B7 10MHz 16QAM Low Channel RB1-0



LTE B7 10MHz QPSK Middle Channel RB1-0



LTE B7 10MHz 16QAM Middle Channel RB1-0



LTE B7 10MHz QPSK High Channel RB1-0



LTE B7 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK Low Channel RB1-0



LTE B7 15MHz 16QAM Low Channel RB1-0



LTE B7 15MHz QPSK Middle Channel RB1-0



LTE B7 15MHz 16QAM Middle Channel RB1-0



LTE B7 15MHz QPSK High Channel RB1-0



LTE B7 15MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 20MHz QPSK Low Channel RB1-0



LTE B7 20MHz 16QAM Low Channel RB1-0



LTE B7 20MHz QPSK Middle Channel RB1-0



LTE B7 20MHz 16QAM Middle Channel RB1-0



LTE B7 20MHz QPSK High Channel RB1-0



LTE B7 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.4. ANT 1, LTE BAND 12



LTE B12 1.4MHz QPSK Low Channel RB1-0



LTE B12 1.4MHz 16QAM Low Channel RB1-0



LTE B12 1.4MHz QPSK Middle Channel RB1-0



LTE B12 1.4MHz 16QAM Middle Channel RB1-0



LTE B12 1.4MHz QPSK High Channel RB1-0



LTE B12 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 3MHz QPSK Low Channel RB1-0



LTE B12 3MHz 16QAM Low Channel RB1-0



LTE B12 3MHz QPSK Middle Channel RB1-0



LTE B12 3MHz 16QAM Middle Channel RB1-0



LTE B12 3MHz QPSK High Channel RB1-0



LTE B12 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 5MHz QPSK Low Channel RB1-0



LTE B12 5MHz 16QAM Low Channel RB1-0



LTE B12 5MHz QPSK Middle Channel RB1-0



LTE B12 5MHz 16QAM Middle Channel RB1-0



LTE B12 5MHz QPSK High Channel RB1-0



LTE B12 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 10MHz QPSK Low Channel RB1-0



LTE B12 10MHz 16QAM Low Channel RB1-0



LTE B12 10MHz QPSK Middle Channel RB1-0



LTE B12 10MHz 16QAM Middle Channel RB1-0



LTE B12 10MHz QPSK High Channel RB1-0



LTE B12 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.5. ANT 1, LTE BAND 13



LTE B13 5MHz QPSK Low Channel RB1-0



LTE B13 5MHz 16QAM Low Channel RB1-0



LTE B13 5MHz QPSK Middle Channel RB1-0



LTE B13 5MHz 16QAM Middle Channel RB1-0



LTE B13 5MHz QPSK High Channel RB1-0



LTE B13 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B13 10MHz QPSK Middle Channel RB1-0



LTE B13 10MHz 16QAM Middle Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.6. ANT 1, LTE BAND 14



LTE B14 5MHz QPSK Low Channel RB1-0



LTE B14 5MHz 16QAM Low Channel RB1-0



LTE B14 5MHz QPSK Middle Channel RB1-0



LTE B14 5MHz 16QAM Middle Channel RB1-0



LTE B14 5MHz QPSK High Channel RB1-0



LTE B14 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B14 10MHz QPSK Middle Channel RB1-0



LTE B14 10MHz 16QAM Middle Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.7. ANT 1, LTE BAND 17



LTE B17 5MHz QPSK Low Channel RB1-0



LTE B17 5MHz 16QAM Low Channel RB1-0



LTE B17 5MHz QPSK Middle Channel RB1-0



LTE B17 5MHz 16QAM Middle Channel RB1-0



LTE B17 5MHz QPSK High Channel RB1-0



LTE B17 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 10MHz QPSK Low Channel RB1-0



LTE B17 10MHz 16QAM Low Channel RB1-0



LTE B17 10MHz QPSK Middle Channel RB1-0



LTE B17 10MHz 16QAM Middle Channel RB1-0



LTE B17 10MHz QPSK High Channel RB1-0



LTE B17 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.8. ANT 1, LTE BAND 25



LTE B25 1.4MHz QPSK Low Channel RB1-0



LTE B25 1.4MHz 16QAM Low Channel RB1-0



LTE B25 1.4MHz QPSK Middle Channel RB1-0



LTE B25 1.4MHz 16QAM Middle Channel RB1-0



LTE B25 1.4MHz QPSK High Channel RB1-0



LTE B25 1.4MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 3MHz QPSK Low Channel RB1-0



LTE B25 3MHz 16QAM Low Channel RB1-0



LTE B25 3MHz QPSK Middle Channel RB1-0



LTE B25 3MHz 16QAM Middle Channel RB1-0



LTE B25 3MHz QPSK High Channel RB1-0



LTE B25 3MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 5MHz QPSK Low Channel RB1-0



LTE B25 5MHz 16QAM Low Channel RB1-0



LTE B25 5MHz QPSK Middle Channel RB1-0



LTE B25 5MHz 16QAM Middle Channel RB1-0



LTE B25 5MHz QPSK High Channel RB1-0



LTE B25 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz QPSK Low Channel RB1-0



LTE B25 10MHz 16QAM Low Channel RB1-0



LTE B25 10MHz QPSK Middle Channel RB1-0



LTE B25 10MHz 16QAM Middle Channel RB1-0



LTE B25 10MHz QPSK High Channel RB1-0



LTE B25 10MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 15MHz QPSK Low Channel RB1-0



LTE B25 15MHz 16QAM Low Channel RB1-0



LTE B25 15MHz QPSK Middle Channel RB1-0



LTE B25 15MHz 16QAM Middle Channel RB1-0



LTE B25 15MHz QPSK High Channel RB1-0



LTE B25 15MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 20MHz QPSK Low Channel RB1-0



LTE B25 20MHz 16QAM Low Channel RB1-0



LTE B25 20MHz QPSK Middle Channel RB1-0



LTE B25 20MHz 16QAM Middle Channel RB1-0



LTE B25 20MHz QPSK High Channel RB1-0



LTE B25 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.9. ANT 1, LTE BAND 26 (PART 90S)



LTE B26 1.4MHz QPSK Low Channel RB1-0



LTE B26 1.4MHz 16QAM Low Channel RB1-0



LTE B26 1.4MHz QPSK Middle Channel RB1-0



LTE B26 1.4MHz 16QAM Middle Channel RB1-0



LTE B26 1.4MHz QPSK High Channel RB1-0



LTE B26 1.4MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 3MHz QPSK Low Channel RB1-0



LTE B26 3MHz 16QAM Low Channel RB1-0



LTE B26 3MHz QPSK Middle Channel RB1-0



LTE B26 3MHz 16QAM Middle Channel RB1-0



LTE B26 3MHz QPSK High Channel RB1-0



LTE B26 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 5MHz QPSK Low Channel RB1-0



LTE B26 5MHz 16QAM Low Channel RB1-0



LTE B26 5MHz QPSK Middle Channel RB1-0



LTE B26 5MHz 16QAM Middle Channel RB1-0



LTE B26 5MHz QPSK High Channel RB1-0



LTE B26 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 10MHz QPSK Middle Channel RB1-0



LTE B26 10MHz 16QAM Middle Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.10. ANT 1, LTE BAND 30



LTE B30 5MHz QPSK Low Channel RB1-0



LTE B30 5MHz 16QAM Low Channel RB1-0



LTE B30 5MHz QPSK Low Channel RB1-0



LTE B30 5MHz 16QAM Low Channel RB1-0



LTE B30 5MHz QPSK Mid Channel RB1-0



LTE B30 5MHz 16QAM Mid Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 5MHz QPSK Middle Channel RB1-0



LTE B30 5MHz 16QAM Middle Channel RB1-0



LTE B30 5MHz QPSK High Channel RB1-0



LTE B30 5MHz 16QAM High Channel RB1-0



LTE B30 10MHz QPSK High Channel RB1-0



LTE B30 10MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 10MHz QPSK Middle Channel RB1-0



LTE B30 10MHz 16QAM Middle Channel RB1-0



LTE B30 10MHz QPSK Mid Channel RB1-0



LTE B30 10MHz 16QAM Mid Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.11. ANT 1, LTE BAND 41



LTE B41 5MHz QPSK Low Channel RB1-0



LTE B41 5MHz 16QAM Low Channel RB1-0



LTE B41 5MHz QPSK Middle Channel RB1-0



LTE B41 5MHz 16QAM Middle Channel RB1-0



LTE B41 5MHz QPSK High Channel RB1-0



LTE B41 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK Low Channel RB1-0



LTE B41 10MHz 16QAM Low Channel RB1-0



LTE B41 10MHz QPSK Middle Channel RB1-0



LTE B41 10MHz 16QAM Middle Channel RB1-0



LTE B41 10MHz QPSK High Channel RB1-0



LTE B41 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK Low Channel RB1-0



LTE B41 15MHz 16QAM Low Channel RB1-0



LTE B41 15MHz QPSK Middle Channel RB1-0



LTE B41 15MHz 16QAM Middle Channel RB1-0



LTE B41 15MHz QPSK High Channel RB1-0



LTE B41 15MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.