

LTE B13 10MHz QPSK Middle Channel RB1-0



LTE B13 10MHz 16QAM Middle Channel RB1-0



LTE B13 10MHz QPSK Middle Channel RB1-49



LTE B13 10MHz 16QAM Middle Channel RB1-49



LTE B13 10MHz QPSK Middle Channel RB50-0



LTE B13 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.7. LTE BAND 14 ADJACENT CHANNEL POWER



LTE B14 5MHz QPSK Low Channel RB1-0



LTE B14 5MHz QPSK High Channel RB1-24



LTE B14 5MHz QPSK Low Channel RB25-0



LTE B14 5MHz QPSK High Channel RB25-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B14 5MHz 16QAM Low Channel RB1-0



LTE B14 5MHz 16QAM High Channel RB1-24



LTE B14 5MHz 16QAM Low Channel RB25-0



LTE B14 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B14 10MHz QPSK Middle Channel RB1-0



LTE B14 10MHz 16QAM Middle Channel RB1-0



LTE B14 10MHz QPSK Middle Channel RB1-49



LTE B14 10MHz 16QAM Middle Channel RB1-49



LTE B14 10MHz QPSK Middle Channel RB50-0



LTE B14 10MHz 16QAM Middle Channel RB50-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.8. LTE BAND 17 BANDEDGE



LTE B17 5MHz QPSK Low Channel RB1-0



LTE B17 5MHz QPSK High Channel RB1-24



LTE B17 5MHz QPSK Low Channel RB25-0



LTE B17 5MHz QPSK High Channel RB25-0



LTE B17 5MHz 16QAM Low Channel RB1-0



LTE B17 5MHz 16QAM High Channel RB1-24

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 5MHz 16QAM Low Channel RB25-0



LTE B17 5MHz 16QAM High Channel RB25-0



LTE B17 10MHz QPSK Low Channel RB1-0



LTE B17 10MHz QPSK High Channel RB1-49



LTE B17 10MHz QPSK Low Channel RB50-0



LTE B17 10MHz QPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 10MHz 16QAM Low Channel RB1-0



LTE B17 10MHz 16QAM High Channel RB1-49



LTE B17 10MHz 16QAM Low Channel RB50-0



LTE B17 10MHz 16QAM High Channel RB50-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.9. LTE BAND 25 BANDEDGE



LTE B25 1.4MHz QPSK Low Channel RB1-0



LTE B25 1.4MHz QPSK High Channel RB1-5



LTE B25 1.4MHz QPSK Low Channel RB6-0



LTE B25 1.4MHz QPSK High Channel RB6-0



LTE B25 1.4MHz 16QAM Low Channel RB1-0



LTE B25 1.4MHz 16QAM High Channel RB1-5

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 1.4MHz 16QAM Low Channel RB6-0



LTE B25 1.4MHz 16QAM High Channel RB6-0



LTE B25 3MHz QPSK Low Channel RB1-0



LTE B25 3MHz QPSK High Channel RB1-14



LTE B25 3MHz QPSK Low Channel RB15-0



LTE B25 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 3MHz 16QAM Low Channel RB1-0



LTE B25 3MHz 16QAM High Channel RB1-14



LTE B25 3MHz 16QAM Low Channel RB15-0



LTE B25 3MHz 16QAM High Channel RB15-0



LTE B25 5MHz QPSK Low Channel RB1-0



LTE B25 5MHz QPSK High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 5MHz QPSK Low Channel RB25-0



LTE B25 5MHz QPSK High Channel RB25-0



LTE B25 5MHz 16QAM Low Channel RB1-0



LTE B25 5MHz 16QAM High Channel RB1-24



LTE B25 5MHz 16QAM Low Channel RB25-0



LTE B25 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz QPSK Low Channel RB1-0



LTE B25 10MHz QPSK High Channel RB1-49



LTE B25 10MHz QPSK Low Channel RB50-0



LTE B25 10MHz QPSK High Channel RB50-0



LTE B25 10MHz 16QAM Low Channel RB1-0



LTE B25 10MHz 16QAM High Channel RB1-49

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz 16QAM Low Channel RB50-0



LTE B25 10MHz 16QAM High Channel RB50-0



LTE B25 15MHz QPSK Low Channel RB1-0



LTE B25 15MHz QPSK High Channel RB1-74



LTE B25 15MHz QPSK Low Channel RB75-0



LTE B25 15MHz QPSK High Channel RB75-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 15MHz 16QAM Low Channel RB1-0



LTE B25 15MHz 16QAM High Channel RB1-74



LTE B25 15MHz 16QAM Low Channel RB75-0



LTE B25 15MHz 16QAM High Channel RB75-0



LTE B25 20MHz QPSK Low Channel RB1-0



LTE B25 20MHz QPSK High Channel RB1-99

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 20MHz QPSK Low Channel RB100-0



LTE B25 20MHz QPSK High Channel RB100-0



LTE B25 20MHz 16QAM Low Channel RB1-0



LTE B25 20MHz 16QAM High Channel RB1-99



LTE B25 20MHz 16QAM Low Channel RB100-0



LTE B25 20MHz 16QAM High Channel RB100-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.10. LTE BAND 26 EMISSION MASK (PART 90S)



LTE B26 1.4MHz QPSK Low Channel RB1-0



LTE B26 1.4MHz QPSK High Channel RB1-5



LTE B26 1.4MHz QPSK Low Channel RB6-0



LTE B26 1.4MHz QPSK High Channel RB6-0



LTE B26 1.4MHz 16QAM Low Channel RB1-0



LTE B26 1.4MHz 16QAM High Channel RB1-5

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 1.4MHz 16QAM Low Channel RB6-0



LTE B26 1.4MHz 16QAM High Channel RB6-0



LTE B26 3MHz QPSK Low Channel RB1-0



LTE B26 3MHz QPSK High Channel RB1-14



LTE B26 3MHz QPSK Low Channel RB15-0



LTE B26 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 3MHz 16QAM Low Channel RB1-0



LTE B26 3MHz 16QAM High Channel RB1-14



LTE B26 3MHz 16QAM Low Channel RB15-0



LTE B26 3MHz 16QAM High Channel RB15-0



LTE B26 5MHz QPSK Low Channel RB1-0



LTE B26 5MHz QPSK High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 5MHz QPSK Low Channel RB25-0



LTE B26 5MHz QPSK High Channel RB25-0



LTE B26 5MHz 16QAM Low Channel RB1-0



LTE B26 5MHz 16QAM High Channel RB1-24



LTE B26 5MHz 16QAM Low Channel RB25-0



LTE B26 5MHz 16QAM High Channel RB25-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 10MHz QPSK Middle Channel RB1-0



LTE B26 10MHz 16QAM Middle Channel RB1-0



LTE B26 10MHz QPSK Middle Channel RB1-49



LTE B26 10MHz 16QAM Middle Channel RB1-49



LTE B26 10MHz QPSK Middle Channel RB50-0



LTE B26 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.11. LTE BAND 30 ADJACENT CHANNEL POWER



LTE B30 5MHz QPSK Low Channel RB1-0



LTE B30 5MHz QPSK High Channel RB1-24



LTE B30 5MHz QPSK Low Channel RB25-0



LTE B30 5MHz QPSK High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 5MHz 16QAM Low Channel RB1-0



LTE B30 5MHz 16QAM High Channel RB1-24



LTE B30 5MHz 16QAM Low Channel RB25-0



LTE B30 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 10MHz QPSK Middle Channel RB1-0



LTE B30 10MHz 16QAM Middle Channel RB1-0



LTE B30 10MHz QPSK Middle Channel RB1-49



LTE B30 10MHz 16QAM Middle Channel RB1-49



LTE B30 10MHz QPSK Middle Channel RB50-0



LTE B30 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.12. LTE BAND 41 ADJACENT CHANNEL POWER

ID:	39004	Date:	5/29-6/22-2018



LTE B41 5MHz QPSK Low Channel RB1-0



LTE B41 5MHz 16QAM Low Channel RB1-0



LTE B41 5MHz QPSK Low Channel RB1-24



LTE B41 5MHz 16QAM Low Channel RB1-24



LTE B41 5MHz QPSK Low Channel RB25-0



LTE B41 5MHz 16QAM Low Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 5MHz QPSK Middle Channel RB1-0



LTE B41 5MHz 16QAM Middle Channel RB1-0



LTE B41 5MHz QPSK Middle Channel RB1-24



LTE B41 5MHz 16QAM Middle Channel RB1-24



LTE B41 5MHz QPSK Middle Channel RB25-0



LTE B41 5MHz 16QAM Middle Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.