

LTE B2 3MHz QPSK Low Channel RB1-0



LTE B2 3MHz 16QAM Low Channel RB1-0



LTE B2 3MHz QPSK Middle Channel RB1-0



LTE B2 3MHz 16QAM Middle Channel RB1-0



LTE B2 3MHz QPSK High Channel RB1-0



LTE B2 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 5MHz QPSK Low Channel RB1-0



LTE B2 5MHz 16QAM Low Channel RB1-0



LTE B2 5MHz QPSK Middle Channel RB1-0



LTE B2 5MHz 16QAM Middle Channel RB1-0



LTE B2 5MHz QPSK High Channel RB1-0



LTE B2 5MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 10MHz QPSK Low Channel RB1-0



LTE B2 10MHz 16QAM Low Channel RB1-0



LTE B2 10MHz QPSK Middle Channel RB1-0



LTE B2 10MHz 16QAM Middle Channel RB1-0



LTE B2 10MHz QPSK High Channel RB1-0



LTE B2 10MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 15MHz QPSK Low Channel RB1-0



LTE B2 15MHz 16QAM Low Channel RB1-0



LTE B2 15MHz QPSK Middle Channel RB1-0



LTE B2 15MHz 16QAM Middle Channel RB1-0



LTE B2 15MHz QPSK High Channel RB1-0



LTE B2 15MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B2 20MHz QPSK Low Channel RB1-0



LTE B2 20MHz 16QAM Low Channel RB1-0



LTE B2 20MHz QPSK Middle Channel RB1-0



LTE B2 20MHz 16QAM Middle Channel RB1-0



LTE B2 20MHz QPSK High Channel RB1-0



LTE B2 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.2. LTE BAND 5



LTE B5 1.4MHz QPSK Low Channel RB1-0



LTE B5 1.4MHz 16QAM Low Channel RB1-0



LTE B5 1.4MHz QPSK Middle Channel RB1-0



LTE B5 1.4MHz 16QAM Middle Channel RB1-0



LTE B5 1.4MHz QPSK High Channel RB1-0



LTE B5 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 3MHz QPSK Low Channel RB1-0



LTE B5 3MHz 16QAM Low Channel RB1-0



LTE B5 3MHz QPSK Middle Channel RB1-0



LTE B5 3MHz 16QAM Middle Channel RB1-0



LTE B5 3MHz QPSK High Channel RB1-0



LTE B5 3MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 5MHz QPSK Low Channel RB1-0



LTE B5 5MHz 16QAM Low Channel RB1-0



LTE B5 5MHz QPSK Middle Channel RB1-0



LTE B5 5MHz 16QAM Middle Channel RB1-0



LTE B5 5MHz QPSK High Channel RB1-0



LTE B5 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 10MHz QPSK Low Channel RB1-0

LTE B5 10MHz 16QAM Low Channel RB1-0



LTE B5 10MHz QPSK Middle Channel RB1-0



LTE B5 10MHz 16QAM Middle Channel RB1-0



LTE B5 10MHz QPSK High Channel RB1-0



LTE B5 10MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.3. LTE BAND 7



LTE B7 5MHz QPSK Low Channel RB1-0



LTE B7 5MHz 16QAM Low Channel RB1-0



LTE B7 5MHz QPSK Middle Channel RB1-0



LTE B7 5MHz 16QAM Middle Channel RB1-0



LTE B7 5MHz QPSK High Channel RB1-0



LTE B7 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.