

LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Antenna 4, LEGACY SISO MODE: 242-Tones, RU index 61

Channel	Frequency (MHz)	99% Bandwidth (MHz)
Low 1	2412	18.9070
Low 2	2417	18.9660
Low 3	2422	18.9680
Mid 6	2437	19.0370
High 9	2452	19.0140
High 10	2457	19.0090
High 11	2462	18.9110
High 12	2467	18.9250
High 13	2472	18.9060

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Antenna 3, LEGACY SISO MODE: 26-Tones, RU index 0

Channel	Frequency (MHz)	99% Bandwidth (MHz)
Low 1	2412	18.4760
Low 2	2417	18.4900
Low 3	2422	18.4570
Mid 6	2437	18.4700
High 9	2452	18.5010
High 10	2457	18.4890
High 11	2462	18.2860
High 12	2467	18.3470
High 13	2472	18.3210

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Antenna 3, LEGACY SISO MODE: 26-Tones, RU index 4

Channel	Frequency (MHz)	99% Bandwidth (MHz)
Low 1	2412	17.2580
Low 2	2417	17.1010
Low 3	2422	17.0990
Mid 6	2437	17.2840
High 9	2452	17.1400
High 10	2457	17.1800
High 11	2462	17.0900
High 12	2467	17.1760
High 13	2472	17.2150

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Antenna 3, LEGACY SISO MODE: 26-Tones, RU index 8

Channel	Frequency (MHz)	99% Bandwidth (MHz)
Low 1	2412	18.6260
Low 2	2417	18.6580
Low 3	2422	18.7310
Mid 6	2437	18.8520
High 9	2452	18.7190
High 10	2457	18.6750
High 11	2462	18.8510
High 12	2467	18.8990
High 13	2472	18.8320

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Antenna 3, LEGACY SISO MODE: 242-Tones, RU index 61

Channel	Frequency (MHz)	99% Bandwidth (MHz)
Low 1	2412	18.8710
Low 2	2417	18.9650
Low 3	2422	18.9620
Mid 6	2437	19.0260
High 9	2452	18.9500
High 10	2457	18.9650
High 11	2462	18.9760
High 12	2467	19.0040
High 13	2472	18.9030

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1



LOW CHANNEL 2



LOW CHANNEL 3



MID CHANNEL 6



HIGH CHANNEL 9



HIGH CHANNEL 10

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 11



HIGH CHANNEL 12



HIGH CHANNEL 13

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.1. 802.11ax HE20 OFDMA MODE 2TX

Antenna 4 + Antenna 3 2TX MODE: 26-Tones, RU Index 0

Channel	Frequency (MHz)	99% Bandwidth Ant 4 (MHz)	99% Bandwidth Ant 3 (MHz)
Low 1	2412	18.5460	18.4060
Low 2	2417	18.5590	18.3860
Low 3	2422	18.5150	18.3770
Low 4	2427	18.4460	18.4310
Mid 6	2437	18.4580	18.3630
High 9	2452	18.6020	18.3450
High 10	2457	18.5140	18.2160
High 11	2462	18.3530	18.2010
High 12	2467	18.2570	18.1630
High 13	2472	18.4060	18.2110

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1 ANT 4



LOW CHANNEL 1 ANT 3



LOW CHANNEL 2 ANT 4



LOW CHANNEL 2 ANT 3



LOW CHANNEL 3 ANT 4



LOW CHANNEL 3 ANT 3

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 4 ANT 4



LOW CHANNEL 4 ANT 3



MID CHANNEL 6 ANT 4



MID CHANNEL 6 ANT 3



HIGH CHANNEL 9 ANT 4



HIGH CHANNEL 9 ANT 3

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.