

LTE B30 5MHz QPSK Middle Channel RB1-0



LTE B30 5MHz 16QAM Middle Channel RB1-0



LTE B30 5MHz QPSK High Channel RB1-0



LTE B30 5MHz 16QAM High Channel RB1-0



LTE B30 5MHz QPSK High Channel RB1-0



LTE B30 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 10MHz QPSK Middle Channel RB1-0



LTE B30 10MHz 16QAM Middle Channel RB1-0



LTE B30 10MHz QPSK Middle Channel RB1-0



LTE B30 10MHz 16QAM Middle Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.11. LTE BAND 41



LTE B41 5MHz QPSK Low Channel RB1-0



LTE B41 5MHz 16QAM Low Channel RB1-0



LTE B41 5MHz QPSK Middle Channel RB1-0



LTE B41 5MHz 16QAM Middle Channel RB1-0



LTE B41 5MHz QPSK High Channel RB1-0



LTE B41 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK Low Channel RB1-0



LTE B41 10MHz 16QAM Low Channel RB1-0



LTE B41 10MHz QPSK Middle Channel RB1-0



LTE B41 10MHz 16QAM Middle Channel RB1-0



LTE B41 10MHz QPSK High Channel RB1-0



LTE B41 10MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK Low Channel RB1-0



LTE B41 15MHz 16QAM Low Channel RB1-0



LTE B41 15MHz QPSK Middle Channel RB1-0



LTE B41 15MHz 16QAM Middle Channel RB1-0



LTE B41 15MHz QPSK High Channel RB1-0



LTE B41 15MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 20MHz QPSK Low Channel RB1-0



LTE B41 20MHz 16QAM Low Channel RB1-0



LTE B41 20MHz QPSK Middle Channel RB1-0



LTE B41 20MHz 16QAM Middle Channel RB1-0



LTE B41 20MHz QPSK High Channel RB1-0



LTE B41 20MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.12. LTE BAND 48



LTE B48 5MHz QPSK Low Channel RB1-0



LTE B48 5MHz QPSK Low Channel RB1-0



LTE B48 5MHz QPSK Middle Channel RB1-0



LTE B48 5MHz QPSK Middle Channel RB1-0



LTE B48 5MHz QPSK High Channel RB1-0



LTE B48 5MHz QPSK High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 5MHz 16QAM Low Channel RB1-0



LTE B48 5MHz 16QAM Low Channel RB1-0



LTE B48 5MHz 16QAM Middle Channel RB1-0



LTE B48 5MHz 16QAM Middle Channel RB1-0



LTE B48 5MHz 16QAM High Channel RB1-0



LTE B48 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 10MHz QPSK Low Channel RB1-0



LTE B48 10MHz QPSK Low Channel RB1-0



LTE B48 10MHz QPSK Middle Channel RB1-0



LTE B48 10MHz QPSK Middle Channel RB1-0



LTE B48 10MHz QPSK High Channel RB1-0



LTE B48 10MHz QPSK High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 10MHz 16QAM Low Channel RB1-0



LTE B48 10MHz 16QAM Low Channel RB1-0



LTE B48 10MHz 16QAM Middle Channel RB1-0



LTE B48 10MHz 16QAM Middle Channel RB1-0



LTE B48 10MHz 16QAM High Channel RB1-0



LTE B48 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 15MHz QPSK Low Channel RB1-0



LTE B48 15MHz QPSK Low Channel RB1-0



LTE B48 15MHz QPSK Middle Channel RB1-0



LTE B48 15MHz QPSK Middle Channel RB1-0



LTE B48 15MHz QPSK High Channel RB1-0



LTE B48 15MHz QPSK High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 15MHz 16QAM Low Channel RB1-0



LTE B48 15MHz 16QAM Low Channel RB1-0



LTE B48 15MHz 16QAM Middle Channel RB1-0



LTE B48 15MHz 16QAM Middle Channel RB1-0



LTE B48 15MHz 16QAM High Channel RB1-0



LTE B48 15MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 20MHz QPSK Low Channel RB1-0



LTE B48 20MHz QPSK Low Channel RB1-0



LTE B48 20MHz QPSK Middle Channel RB1-0



LTE B48 20MHz QPSK Middle Channel RB1-0



LTE B48 20MHz QPSK High Channel RB1-0



LTE B48 20MHz QPSK High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 20MHz 16QAM Low Channel RB1-0



LTE B48 20MHz 16QAM Low Channel RB1-0



LTE B48 20MHz 16QAM Middle Channel RB1-0



LTE B48 20MHz 16QAM Middle Channel RB1-0



LTE B48 20MHz 16QAM High Channel RB1-0



LTE B48 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.3.13. LTE BAND 66



LTE B66 1.4MHz QPSK Low Channel RB1-0



LTE B66 1.4MHz 16QAM Low Channel RB1-0



LTE B66 1.4MHz QPSK Middle Channel RB1-0



LTE B66 1.4MHz 16QAM Middle Channel RB1-0



LTE B66 1.4MHz QPSK High Channel RB1-0



LTE B66 1.4MHz 16QAM High Channel RB1-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.