5G NR n25



5G NR n25 5MHz BPSK Middle Channel RB25-0 ID:28498



5G NR n25 10MHz BPSK Middle Channel RB50-0 ID:28498



5G NR n25 15MHz BPSK Middle Channel RB75-0 ID:28498



5G NR n25 20MHz BPSK Middle Channel RB100-0 ID:28498



5G NR n25 25MHz BPSK Middle Channel RB128-0 ID:28498



5G NR n25 30MHz BPSK Middle Channel RB160-0 ID:28498

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n25 40MHz BPSK Middle Channel RB216-0 ID:28498



5G NR n25 40MHz BPSK Middle Channel RB1-0 ID:28498

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.7. LTE BAND 26 AND 5G NR n26 (PART 90S)

LTE BAND 26



LTE B26 1.4MHz QPSK Middle Channel RB6-0 ID:19210



LTE B26 3MHz QPSK Middle Channel RB15-0 ID:19210



LTE B26 5MHz QPSK Middle Channel RB25-0 ID:19210



LTE B26 10MHz QPSK Middle Channel RB50-0 ID:19210



LTE B26 10MHz QPSK Middle Channel RB1-0 ID:19210

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n26



5G NR n26 5MHz BPSK Middle Channel RB25-0 ID:28498



5G NR n26 10MHz BPSK Middle Channel RB50-0 ID:28498



5G NR n26 10MHz BPSK Middle Channel RB75-0 ID:28498

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.8. LTE BAND 26 AND 5G NR n26 (PART 22)

LTE BAND 26



LTE B26 1.4MHz QPSK Middle Channel RB6-0 ID:28498



LTE B26 3MHz QPSK Middle Channel RB15-0 ID:28498



LTE B26 5MHz QPSK Middle Channel RB25-0 ID:28498



LTE B26 10MHz QPSK Middle Channel RB50-0 ID:28498



LTE B26 15MHz QPSK Middle Channel RB75-0 ID:28498



LTE B26 15MHz QPSK Middle Channel RB1-0 ID:28498

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n26



5G NR n26 5MHz BPSK Middle Channel RB25-0 ID:19210



5G NR n26 10MHz BPSK Middle Channel RB50-0 ID:19210



5G NR n26 15MHz BPSK Middle Channel RB75-0 ID:19210



5G NR n26 20MHz BPSK Middle Channel RB100-0 ID:19210



5G NR n26 20MHz Middle High Channel RB1-0 ID:19210

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.9. LTE BAND 30 AND 5G NR n30



LTE B30 5MHz QPSK Middle Channel RB25-0 ID:28567

LTE B30 10MHz QPSK Middle Channel RB50-0 ID:28567



LTE B30 10MHz QPSK Middle Channel RB1-0 ID:28567

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n30



5G NR n30 5MHz BPSK Middle Channel RB25-0 ID:28498



5G NR n30 10MHz BPSK Middle Channel RB50-0 ID:28498



5G NR n30 10MHz BPSK Middle Channel RB1-0 ID:28498

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.10. LTE BAND 41 AND 5G NR n41

LTE BAND 41

LTE B41 5MHz QPSK Middle Channel RB25-0 ID:28567

LTE B41 10MHz QPSK Middle Channel RB50-0 ID:28567



LTE B41 15MHz QPSK Middle Channel RB75-0 ID:28567



LTE B41 20MHz QPSK Middle Channel RB100-0 ID:28567



LTE B41 20MHz QPSK Middle Channel RB1-0 ID:28567

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n41



5G NR n41 10MHz BPSK Middle Channel RB24-0 ID:28498



5G NR n41 15MHz BPSK Middle Channel RB36-0 ID:28498



5G NR n41 20MHz BPSK Middle Channel RB50-0



5G NR n41 30MHz BPSK Middle Channel RB75-0 ID:28498



5G NR n41 40MHz BPSK Middle Channel RB100-0 ID:28498



5G NR n41 50MHz BPSK Middle Channel RB128-0 ID:28498

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK Middle Channel RB162-0 ID:28498



5G NR n41 70MHz BPSK Middle Channel RB180-0 ID:28498



5G NR n41 80MHz BPSK Middle Channel RB216-0 ID:28498



5G NR n41 90MHz BPSK Middle Channel RB243-0 ID:28498



5G NR n41 100MHz BPSK Middle Channel RB270-0 ID:28498



5G NR n41 100MHz BPSK Middle Channel RB1-0 ID:28498

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.11. LTE BAND 48 AND 5G NR n48

LTE BAND 48



LTE B48 5MHz QPSK Middle Channel RB25-0 ID:28567



LTE B48 10MHz QPSK Middle Channel RB50-0 ID:28567



LTE B48 15MHz QPSK Middle Channel RB75-0 ID:28567



LTE B48 20MHz QPSK Middle Channel RB100-0 ID:28567



LTE B48 20MHz QPSK Middle Channel RB1-0 ID:28567

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n48



5G NR n48 10MHz BPSK Middle Channel RB24-0 ID:28498



5G NR n48 15MHz BPSK Middle Channel RB36-0 ID:28498



5G NR n48 20MHz BPSK Middle Channel RB50-0 ID:28498



5G NR n48 30MHz BPSK Middle Channel RB75-0 ID:28498



5G NR n48 40MHz BPSK Middle Channel RB100-0 ID:28498



5G NR n48 40MHz BPSK Middle Channel RB1-0 ID:28498

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.