

LTE B66 10MHz QPSK Low Channel RB1-0, ID:25780



LTE B66 10MHz QPSK High Channel RB1-49, ID:25780



LTE B66 10MHz QPSK Low Channel RB50-0, ID:25780



LTE B66 10MHz QPSK High Channel RB50-0, ID:25780



LTE B66 15MHz QPSK Low Channel RB1-0, ID:25780



LTE B66 15MHz QPSK High Channel RB1-74, ID:25780

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 15MHz QPSK Low Channel RB75-0, ID:25780



LTE B66 15MHz QPSK High Channel RB75-0, ID:25780



LTE B66 20MHz QPSK Low Channel RB1-0, ID:25780



LTE B66 20MHz QPSK High Channel RB1-99, ID:25780



LTE B66 20MHz QPSK Low Channel RB100-0, ID:25780



LTE B66 20MHz QPSK High Channel RB100-0, ID:25780

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n66 BANDEDGE



5G NR n66 5MHz BPSK Low Channel RB1-0, ID:50822



5G NR n66 5MHz BPSK High Channel RB1-24, ID:50822



5G NR n66 5MHz BPSK Low Channel RB25-0, ID:50822



5G NR n66 5MHz BPSK High Channel RB25-0, ID:50822



5G NR n66 10MHz BPSK Low Channel RB1-0, ID:50822



5G NR n66 10MHz BPSK High Channel RB1-51, ID:50822

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 10MHz BPSK Low Channel RB50-0, ID:50822



5G NR n66 10MHz BPSK High Channel RB50-0, ID:50822



5G NR n66 15MHz BPSK Low Channel RB1-0, ID:50822



5G NR n66 15MHz BPSK High Channel RB1-78, ID:50822



5G NR n66 15MHz BPSK Low Channel RB75-0, ID:50822



5G NR n66 15MHz BPSK High Channel RB75-0, ID:50822

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 20MHz BPSK Low Channel RB1-0, ID:50822



5G NR n66 20MHz BPSK High Channel RB1-105, ID:50822



5G NR n66 20MHz BPSK Low Channel RB100-0, ID:50822



5G NR n66 20MHz BPSK High Channel RB100-0, ID:50822



5G NR n66 25MHz BPSK Low Channel RB1-0



5G NR n66 25MHz BPSK High Channel RB1-132

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 25MHz BPSK Low Channel RB128-0



5G NR n66 25MHz BPSK High Channel RB128-0



5G NR n66 30MHz BPSK Low Channel RB1-0, ID:50822

5G NR n66 30MHz BPSK High Channel RB1-159, ID:50822



5G NR n66 30MHz BPSK Low Channel RB160-0, ID:50822



5G NR n66 30MHz BPSK High Channel RB160-0, ID:50822

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 35MHz BPSK Low Channel RB1-0



5G NR n66 35MHz BPSK High Channel RB1-187



5G NR n66 35MHz BPSK Low Channel RB180-0



5G NR n66 35MHz BPSK High Channel RB180-0



5G NR n66 40MHz BPSK Low Channel RB1-0



5G NR n66 40MHz BPSK High Channel RB1-215

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 40MHz BPSK Low Channel RB216-0



5G NR n66 40MHz BPSK High Channel RB216-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.13. 5G NR n70

LIMITS

FCC: §27.53(h)
The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitting power (P) by a factor of at least 43 + 10 log (P) dB.

NOTE: 20MHz and 25MHz Bandwidth Upper Block Bandedge is covered by 5G NR n66 20MHz and 25MHz Bandwidth.

5G NR n70 EMISSION MASK



5G NR n70 5MHz BPSK Low Channel (Lower Block) RB1-0



5G NR n70 15MHz BPSK Middle Channel (Full Block) RB1-0



5G NR n70 5MHz BPSK Low Channel (Lower Block) RB1-24



NR n70 15MHz BPSK Middle Channel (Full Block) RB1-78

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n70 5MHz BPSK Low Channel (Lower Block) RB25-0



5G NR n70 15MHz BPSK Middle Channel (Full Block) RB75-0



5G NR n70 5MHz BPSK Middle Channel (Upper Block) RB1-0



5G NR n70 5MHz BPSK High Channel (Upper Block) RB1-24



5G NR n70 5MHz BPSK Middle Channel (Upper Block) RB25-0



5G NR n70 5MHz BPSK High Channel (Upper Block) RB25-0,

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n70 10MHz BPSK Low Channel (Full Block) RB1-0



5G NR n70 10MHz BPSK High Channel (Full Block) RB1-51



5G NR n70 10MHz BPSK Low Channel (Full Block) RB50-0



5G NR n70 10MHz BPSK High Channel (Full Block) RB50-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.14. LTE BAND 71 AND 5G NR n71

LIMITS

FCC: §27.53
(g) For operations in the 600 MHz band and the 698-746 MHz band, the power of any emission outside a licensee's frequency band(s) of operation shall be attenuated below the transmitter power (P) within the licensed band(s) of operation, measured in watts, by at least 43 + 10 log (P) dB. Compliance with this provision is based on the use of measurement instrumentation employing a resolution bandwidth of 100 kilohertz or greater. However, in the 100 kilohertz bands immediately outside and adjacent to a licensee's frequency block, a resolution bandwidth of at least 30 kHz may be employed.

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE BAND 71 ADJACENT CHANNEL POWER



LTE B71 5MHz QPSK Low Channel RB1-0



LTE B71 5MHz QPSK Middle Channel RB1-0



LTE B71 5MHz QPSK Low Channel RB1-24



LTE B71 5MHz QPSK Middle Channel RB1-24



LTE B71 5MHz QPSK Low Channel RB25-0



LTE B71 5MHz QPSK Middle Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 5MHz QPSK High Channel RB1-0



LTE B71 10MHz QPSK Low Channel RB1-0



LTE B71 5MHz QPSK High Channel RB1-24



LTE B71 10MHz QPSK Low Channel RB1-49



LTE B71 5MHz QPSK High Channel RB25-0



LTE B71 10MHz QPSK Low Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 10MHz QPSK Middle Channel RB1-0



LTE B71 10MHz QPSK High Channel RB1-0



LTE B71 10MHz QPSK Middle Channel RB1-49



LTE B71 10MHz QPSK High Channel RB1-49



LTE B71 10MHz QPSK Middle Channel RB50-0



LTE B71 10MHz QPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 15MHz QPSK Low Channel RB1-0



LTE B71 15MHz QPSK Middle Channel RB1-0



LTE B71 15MHz QPSK Low Channel RB1-74



LTE B71 15MHz QPSK Middle Channel RB1-74



LTE B71 15MHz QPSK Low Channel RB75-0



LTE B71 15MHz QPSK Middle Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.