5G NR n7 EMISSION MASK



5G NR n7 5MHz BPSK Low Channel RB1-0



5G NR n7 5MHz BPSK Middle Channel RB1-0



5G NR n7 5MHz BPSK Low Channel RB1-24



5G NR n7 5MHz BPSK Middle Channel RB1-24



5G NR n7 5MHz BPSK Low Channel RB25-0



5G NR n7 5MHz BPSK Middle Channel RB25-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 5MHz BPSK High Channel RB1-0



5G NR n7 10MHz BPSK Low Channel RB1-0



5G NR n7 5MHz BPSK High Channel RB1-24



5G NR n7 10MHz BPSK Low Channel RB1-51



5G NR n7 5MHz BPSK High Channel RB25-0



5G NR n7 10MHz BPSK Low Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 10MHz BPSK Middle Channel RB1-0



5G NR n7 10MHz BPSK High Channel RB1-0



5G NR n7 10MHz BPSK Middle Channel RB1-51



5G NR n7 10MHz BPSK High Channel RB1-51



5G NR n7 10MHz BPSK Middle Channel RB50-0



5G NR n7 10MHz BPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 15MHz BPSK Low Channel RB1-0



5G NR n7 15MHz BPSK Middle Channel RB1-0



5G NR n7 15MHz BPSK Low Channel RB1-78



5G NR n7 15MHz BPSK Middle Channel RB1-78



5G NR n7 15MHz BPSK Low Channel RB75-0



5G NR n7 15MHz BPSK Middle Channel RB75-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 15MHz BPSK High Channel RB1-0



5G NR n7 20MHz BPSK Low Channel RB1-0



5G NR n7 15MHz BPSK High Channel RB1-78



5G NR n7 20MHz BPSK Low Channel RB1-105



5G NR n7 15MHz BPSK High Channel RB75-0



5G NR n7 20MHz BPSK Low Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 20MHz BPSK Middle Channel RB1-0



5G NR n7 20MHz BPSK High Channel RB1-0



5G NR n7 20MHz BPSK Middle Channel RB1-105



5G NR n7 20MHz BPSK High Channel RB1-105



5G NR n7 20MHz BPSK Middle Channel RB100-0



5G NR n7 20MHz BPSK High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK Low Channel RB1-0



5G NR n7 25MHz BPSK Middle Channel RB1-0



5G NR n7 25MHz BPSK Low Channel RB1-132



5G NR n7 25MHz BPSK Middle Channel RB1-132



5G NR n7 25MHz BPSK Low Channel RB128-0



5G NR n7 25MHz BPSK Middle Channel RB128-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK High Channel RB1-0



5G NR n7 30MHz BPSK Low Channel RB1-0



5G NR n7 25MHz BPSK High Channel RB1-132



5G NR n7 30MHz BPSK Low Channel RB1-159



5G NR n7 25MHz BPSK High Channel RB128-0



5G NR n7 30MHz BPSK Low Channel RB160-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.