2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 36



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.5.4. 802.11ax HE160 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 36



LOW CHANNEL 6025



MID CHANNEL 6185

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 6345

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index S36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 36



LOW CHANNEL 6025



MID CHANNEL 6185

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 6345

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index S36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index S36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – SU Mode



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index S36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.5.5. 802.11ax HE20 MODE IN THE UNII-6 BAND

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6435



MID CHANNEL 6475



HIGH CHANNEL 6515

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 4



LOW CHANNEL 6435



MID CHANNEL 6475

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 6515

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 8

LOW CHANNEL 6435

MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6435



MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.