1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6435

MID CHANNEL 6475



HIGH CHANNEL 6515

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 4



LOW CHANNEL 6435



MID CHANNEL 6475

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 6515

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 8

LOW CHANNEL 6435



MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6435



MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475

HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 4



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 8



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – SU MODE



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 4



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 8



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.5.6. 802.11ax HE40 MODE IN THE UNII-6 BAND

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0

LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 8



LOW CHANNEL 6445



MID CHANNEL 6485

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



STRADDLE CHANNEL 6525

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 17



LOW CHANNEL 6445

MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6445



MID CHANNEL 6485

STRADDLE CHANNEL 6525

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 8



LOW CHANNEL 6445



MID CHANNEL 6485

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



STRADDLE CHANNEL 6525

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 17



LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6445



LOWCHANNEL ANT 5 6445



MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525



STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 8



LOW CHANNEL ANT 6 6445



LOWCHANNEL ANT 5 6445



MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525



STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.