2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – SU Mode



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 0



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 36



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index S36



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.5.13. 802.11ax HE20 MODE IN THE UNII-8 BAND

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 4



LOW CHANNEL 6895



MID CHANNEL 6995

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 7095

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 8



LOW CHANNEL 6895

MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095



233 CHANNEL 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 4



LOW CHANNEL 6895



MID CHANNEL 6995

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 7095

1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 8



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095



233 CHANNEL 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 4



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 8



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – SU MODE



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



233 CHANNEL ANT 6 7115



233 CHANNEL ANT 5 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 0



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 4



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 8



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



233 CHANNEL ANT 6 7115



233 CHANNEL ANT 5 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.5.14. 802.11ax HE40 MODE IN THE UNII-8 BAND

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0

STRADDLE CHANNEL 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 8



STRADDLE CHANNEL 6885



LOW CHANNEL 6965

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 7085

1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 17



STRADDLE CHANNEL 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



STRADDLE CHANNEL 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.