

LTE B7 10MHz QPSK Middle Channel RB1-0, ID:28567



LTE B7 10MHz QPSK High Channel RB1-0, ID:28567



LTE B7 10MHz QPSK Middle Channel RB1-49, ID:28567



LTE B7 10MHz QPSK High Channel RB1-49, ID:28567



LTE B7 10MHz QPSK Middle Channel RB50-0, ID:28567



LTE B7 10MHz QPSK High Channel RB50-0, ID:28567

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK Low Channel RB1-0, ID:28567



LTE B7 15MHz QPSK Middle Channel RB1-0, ID:28567



LTE B7 15MHz QPSK Low Channel RB1-74, ID:28567



LTE B7 15MHz QPSK Middle Channel RB1-74, ID:28567



LTE B7 15MHz QPSK Low Channel RB75-0, ID:28567



LTE B7 15MHz QPSK Middle Channel RB75-0, ID:28567

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK High Channel RB1-0, ID:28567



LTE B7 20MHz QPSK Low Channel RB1-0, ID:28567



LTE B7 15MHz QPSK High Channel RB1-74, ID:28567



LTE B7 20MHz QPSK Low Channel RB1-99, ID:28567



LTE B7 15MHz QPSK High Channel RB75-0, ID:28567



LTE B7 20MHz QPSK Low Channel RB100-0, ID:28567

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 20MHz QPSK Middle Channel RB1-0, ID:28567



LTE B7 20MHz QPSK High Channel RB1-0, ID:28567



LTE B7 20MHz QPSK Middle Channel RB1-99, ID:28567



LTE B7 20MHz QPSK High Channel RB1-99, ID:28567



LTE B7 20MHz QPSK Middle Channel RB100-0, ID:28567



LTE B7 20MHz QPSK High Channel RB100-0, ID:28567

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n7 EMISSION MASK



5G NR n7 5MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 5MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 5MHz BPSK Low Channel RB1-24, ID:28568



5G NR n7 5MHz BPSK Middle Channel RB1-24, ID:28568



5G NR n7 5MHz BPSK Low Channel RB25-0, ID:28568



5G NR n7 5MHz BPSK Middle Channel RB25-0, ID:28568

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 5MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 10MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 5MHz BPSK High Channel RB1-24, ID:28568



5G NR n7 10MHz BPSK Low Channel RB1-51, ID:28568



5G NR n7 5MHz BPSK High Channel RB25-0, ID:28568



5G NR n7 10MHz BPSK Low Channel RB50-0, ID:28568

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 10MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 10MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 10MHz BPSK Middle Channel RB1-51, ID:28568



5G NR n7 10MHz BPSK High Channel RB1-51, ID:28568



5G NR n7 10MHz BPSK Middle Channel RB50-0, ID:28568



5G NR n7 10MHz BPSK High Channel RB50-0, ID:28568

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 15MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 15MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 15MHz BPSK Low Channel RB1-78, ID:28568



5G NR n7 15MHz BPSK Middle Channel RB1-78, ID:28568



5G NR n7 15MHz BPSK Low Channel RB75-0, ID:28568



5G NR n7 15MHz BPSK Middle Channel RB75-0, ID:28568

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 15MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 20MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 15MHz BPSK High Channel RB1-78, ID:28568



5G NR n7 20MHz BPSK Low Channel RB1-105, ID:28568



5G NR n7 15MHz BPSK High Channel RB75-0, ID:28568



5G NR n7 20MHz BPSK Low Channel RB100-0, ID:28568

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 20MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 20MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 20MHz BPSK Middle Channel RB1-105, ID:28568



5G NR n7 20MHz BPSK High Channel RB1-105, ID:28568



5G NR n7 20MHz BPSK Middle Channel RB100-0, ID:28568



5G NR n7 20MHz BPSK High Channel RB100-0, ID:28568

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 25MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 25MHz BPSK Low Channel RB1-132, ID:28568



5G NR n7 25MHz BPSK Middle Channel RB1-132, ID:28568



5G NR n7 25MHz BPSK Low Channel RB128-0, ID:28568



5G NR n7 25MHz BPSK Middle Channel RB128-0, ID:28568

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 30MHz BPSK Low Channel RB1-0, ID:28568



5G NR n7 25MHz BPSK High Channel RB1-132, ID:28568



5G NR n7 30MHz BPSK Low Channel RB1-159, ID:28568



5G NR n7 25MHz BPSK High Channel RB128-0, ID:28568



5G NR n7 30MHz BPSK Low Channel RB160-0, ID:28568

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 30MHz BPSK Middle Channel RB1-0, ID:28568



5G NR n7 30MHz BPSK High Channel RB1-0, ID:28568



5G NR n7 30MHz BPSK Middle Channel RB1-159, ID:28568



5G NR n7 30MHz BPSK High Channel RB1-159, ID:28568



5G NR n7 30MHz BPSK Middle Channel RB160-0, ID:28568



5G NR n7 30MHz BPSK High Channel RB160-0, ID:28568

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.