2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6115



LOW CHANNEL ANT 5 6115



MID CHANNEL ANT 6 6175



MID CHANNEL ANT 5 6175



HIGH CHANNEL ANT 6 6415



HIGH CHANNEL ANT 5 6415

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.2. 802.11be EHT40 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



LOW CHANNEL 6125



MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



MID CHANNEL 6165

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



LOW CHANNEL 6125



MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6125



MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



LOW CHANNEL 6125

MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



MID CHANNEL 6165

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



LOW CHANNEL 6125



MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6125



MID CHANNEL 6165



HIGH CHANNEL 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 242-Tones, RU Index 61



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 615



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 242-Tones, RU Index 62



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 6165



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 6165



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 53



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 615



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 54



MID CHANNEL ANT 6 6165

MID CHANNEL ANT 5 6165

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 56



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 6165



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6125



LOW CHANNEL ANT 5 6125



MID CHANNEL ANT 6 6165



MID CHANNEL ANT 5 6165



HIGH CHANNEL ANT 6 6405



HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.3. 802.11be EHT80 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 82



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 85



MID CHANNEL 6305

1TX Antenna 6 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 89



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 82



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 85



MID CHANNEL 6305

1TX Antenna 5 MODE (FCC+IC) MOBILE – MRU106+26-Tones, RU Index 89



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6145



MID CHANNEL 6305



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – MRU484+242-Tones, RU Index 90



LOW CHANNEL ANT 6 6145



LOW CHANNEL ANT 5 6145



MID CHANNEL ANT 6 6305



MID CHANNEL ANT 5 6305



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – MRU484+242-Tones, RU Index 92



MID CHANNEL ANT 6 6305



MID CHANNEL ANT 5 6305

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – MRU484+242-Tones, RU Index 93



LOW CHANNEL ANT 6 6145



LOW CHANNEL ANT 5 6145



MID CHANNEL ANT 6 6305



MID CHANNEL ANT 5 6305



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.