2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 54



LOW CHANNEL ANT 6 6535



LOW CHANNEL ANT 5 6535



MID CHANNEL ANT 6 6715



MID CHANNEL ANT 5 6715



HIGH CHANNEL ANT 6 6855



HIGH CHANNEL ANT 5 6855

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6535



LOW CHANNEL ANT 5 6535



MID CHANNEL ANT 6 6715



MID CHANNEL ANT 5 6715



HIGH CHANNEL ANT 6 6855



HIGH CHANNEL ANT 5 6855

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.6. 802.11be EHT40 MODE IN THE UNII-7 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



LOW CHANNEL 6565



MID CHANNEL 6685



HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



MID CHANNEL 6685

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



LOW CHANNEL 6565



MID CHANNEL 6685

HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6565



MID CHANNEL 6685



HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



LOW CHANNEL 6565



MID CHANNEL 6685



HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



MID CHANNEL 6685

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



LOW CHANNEL 6565



MID CHANNEL 6685



HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6565



MID CHANNEL 6685



HIGH CHANNEL 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 242-Tones, RU Index 61



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 242-Tones, RU Index 62



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU MODE



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 53



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 54



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 56



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU MODE



LOW CHANNEL Ant 6 6565



LOW CHANNEL Ant 5 6565



MID CHANNEL ANT 6 6685



MID CHANNEL ANT 5 6685



HIGH CHANNEL ANT 6 6845



HIGH CHANNEL ANT 5 6845

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.7. 802.11be EHT80 MODE IN THE UNII-7 BAND

1TX Antenna 6 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 71



LOW CHANNEL 6625

MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 74



MID CHANNEL 6705

1TX Antenna 6 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 80



LOW CHANNEL 6625



MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6625



MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 71



LOW CHANNEL 6625



MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 74



MID CHANNEL 6705

1TX Antenna 5 MODE (FCC) MOBILE – MRU52+26-Tones, RU Index 80



LOW CHANNEL 6625

MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC) MOBILE – SU MODE



LOW CHANNEL 6625



MID CHANNEL 6705



HIGH CHANNEL 6785

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.