

5G NR n77 15MHz BPSK Low Channel RB1-0 Port A



5G NR n77 15MHz BPSK Low Channel RB1-37 Port A, ID:32061



5G NR n77 15MHz BPSK Low Channel RB1-0 Port B



5G NR n77 15MHz BPSK Low Channel RB1-37 Port B, ID:32061



5G NR n77 15MHz BPSK Low Channel RB1-0 Port A+B



5G NR n77 15MHz BPSK Low Channel RB1-37 Port A+B, ID:32061

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK Middle Channel RB1-0 Port A



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A, ID:32061



5G NR n77 15MHz BPSK Middle Channel RB1-0 Port B



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port B, ID:32061



5G NR n77 15MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A+B, ID:32061

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK High Channel RB1-0 Port A



5G NR n77 15MHz BPSK High Channel RB1-37 Port A



5G NR n77 15MHz BPSK High Channel RB1-0 Port B



5G NR n77 15MHz BPSK High Channel RB1-37 Port B



5G NR n77 15MHz BPSK High Channel RB1-0 Port A+B



5G NR n77 15MHz BPSK High Channel RB1-37 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK Low Channel RB36-0 Port A



5G NR n77 15MHz BPSK Mid Channel RB36-0 Port A



5G NR n77 15MHz BPSK Low Channel RB36-0 Port B



5G NR n77 15MHz BPSK Mid Channel RB36-0 Port B



5G NR n77 15MHz BPSK Low Channel RB36-0 Port A+B



5G NR n77 15MHz BPSK Mid Channel RB36-0 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK High Channel RB36-0 Port A



5G NR n77 15MHz BPSK High Channel RB36-0 Port B



5G NR n77 15MHz BPSK High Channel RB36-0 Port A+B

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB1-0 Port A ID: 32546



5G NR n77 20MHz BPSK Low Channel RB1-50 Port A ID: 32546



5G NR n77 20MHz BPSK Low Channel RB1-0 Port B ID: 32546



5G NR n77 20MHz BPSK Low Channel RB1-50 Port B ID: 32546



5G NR n77 20MHz BPSK Low Channel RB1-0 Port A+B ID: 32546



5G NR n77 20MHz BPSK Low Channel RB1-50 Port A+B ID: 32546

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Middle Channel RB1-0 Port A



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port A ID: 32546



5G NR n77 20MHz BPSK Middle Channel RB1-0 Port B



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port B ID: 32546



5G NR n77 20MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port A+B ID: 32546

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK High Channel RB1-0 Port A



5G NR n77 20MHz BPSK High Channel RB1-50 Port A



5G NR n77 20MHz BPSK High Channel RB1-0 Port B



5G NR n77 20MHz BPSK High Channel RB1-50 Port B



5G NR n77 20MHz BPSK High Channel RB1-0 Port A+B



5G NR n77 20MHz BPSK High Channel RB1-50 Port A+B

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB50-0 Port A



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port A



5G NR n77 20MHz BPSK Low Channel RB50-0 Port B



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port B



5G NR n77 20MHz BPSK Low Channel RB50-0 Port A+B



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port A+B

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.