

5G NR n41 60MHz BPSK Middle Channel RB1-0 Port A



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port A



5G NR n41 60MHz BPSK Middle Channel RB1-0 Port B



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port B



5G NR n41 60MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK High Channel RB1-0 Port A ID: 32546



5G NR n41 60MHz BPSK High Channel RB1-161 Port A ID: 32546



5G NR n41 60MHz BPSK High Channel RB1-0 Port B ID: 32546



5G NR n41 60MHz BPSK High Channel RB1-161 Port B ID: 32546



5G NR n41 60MHz BPSK High Channel RB1-0 Port A+B ID: 32546



5G NR n41 60MHz BPSK High Channel RB1-161 Port A+B ID: 32546

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK Low Channel RB162-0 Port A



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port



5G NR n41 60MHz BPSK Low Channel RB162-0 Port B



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port B



5G NR n41 60MHz BPSK Low Channel RB162-0 Port A+B



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK High Channel RB162-0 Port A ID: 32546



5G NR n41 60MHz BPSK High Channel RB162-0 Port B ID: 32546



5G NR n41 60MHz BPSK High Channel RB162-0 Port A+B ID: 32546

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 70MHz BPSK Low Channel RB1-0 Port A ID: 32546



5G NR n41 70MHz BPSK Low Channel RB1-188 Port A ID: 32546



5G NR n41 70MHz BPSK Low Channel RB1-0 Port B ID: 32546



5G NR n41 70MHz BPSK Low Channel RB1-188 Port B ID: 32546



5G NR n41 70MHz BPSK Low Channel RB1-0 Port A+B ID: 32546



5G NR n41 70MHz BPSK Low Channel RB1-188 Port A+B ID: 32546

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 70MHz BPSK Middle Channel RB1-0 Port A



5G NR n41 70MHz BPSK Mid Channel RB1-188 Port A



5G NR n41 70MHz BPSK Middle Channel RB1-0 Port B



5G NR n41 70MHz BPSK Mid Channel RB1-188 Port B



5G NR n41 70MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n41 70MHz BPSK Mid Channel RB1-188 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 70MHz BPSK High Channel RB1-0 Port A ID: 32546



5G NR n41 70MHz BPSK High Channel RB1-188 Port A ID: 32546



5G NR n41 70MHz BPSK High Channel RB1-0 Port B ID: 32546



5G NR n41 70MHz BPSK High Channel RB1-188 Port B ID: 32546



5G NR n41 70MHz BPSK High Channel RB1-0 Port A+B ID: 32546



5G NR n41 70MHz BPSK High Channel RB1-188 Port A+B ID: 32546

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 70MHz BPSK Low Channel RB180-0 Port A ID: 32546



5G NR n41 70MHz BPSK Mid Channel RB180-0 Port



5G NR n41 70MHz BPSK Low Channel RB180-0 Port B ID: 32546



5G NR n41 70MHz BPSK Mid Channel RB180-0 Port B



5G NR n41 70MHz BPSK Low Channel RB180-0 Port A+B ID: 32546



5G NR n41 70MHz BPSK Mid Channel RB180-0 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 70MHz BPSK High Channel RB180-0 Port A ID: 32546



5G NR n41 70MHz BPSK High Channel RB180-0 Port B ID: 32546



5G NR n41 70MHz BPSK High Channel RB180-0 Port A+B ID: 32546

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.