

5G NR n7 20MHz BPSK Middle Channel RB1-0



5G NR n7 20MHz BPSK High Channel RB1-0



5G NR n7 20MHz BPSK Middle Channel RB1-105



5G NR n7 20MHz BPSK High Channel RB1-105



5G NR n7 20MHz BPSK Middle Channel RB100-0



5G NR n7 20MHz BPSK High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK Low Channel RB1-0



5G NR n7 25MHz BPSK Middle Channel RB1-0



5G NR n7 25MHz BPSK Low Channel RB1-132



5G NR n7 25MHz BPSK Middle Channel RB1-132



5G NR n7 25MHz BPSK Low Channel RB128-0



5G NR n7 25MHz BPSK Middle Channel RB128-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 25MHz BPSK High Channel RB1-0



5G NR n7 30MHz BPSK Low Channel RB1-0



5G NR n7 25MHz BPSK High Channel RB1-132



5G NR n7 30MHz BPSK Low Channel RB1-159



5G NR n7 25MHz BPSK High Channel RB128-0



5G NR n7 30MHz BPSK Low Channel RB160-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 30MHz BPSK Middle Channel RB1-0



5G NR n7 30MHz BPSK High Channel RB1-0



5G NR n7 30MHz BPSK Middle Channel RB1-159



5G NR n7 30MHz BPSK High Channel RB1-159



5G NR n7 30MHz BPSK Middle Channel RB160-0



5G NR n7 30MHz BPSK High Channel RB160-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 35MHz BPSK Low Channel RB1-0



5G NR n7 35MHz BPSK Middle Channel RB1-0



5G NR n7 35MHz BPSK Low Channel RB1-187



5G NR n7 35MHz BPSK Middle Channel RB1-187



5G NR n7 35MHz BPSK Low Channel RB180-0



5G NR n7 35MHz BPSK Middle Channel RB180-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 35MHz BPSK High Channel RB1-0



5G NR n7 40MHz BPSK Low Channel RB1-0



5G NR n7 35MHz BPSK High Channel RB1-187



5G NR n7 40MHz BPSK Low Channel RB1-215



5G NR n7 35MHz BPSK High Channel RB180-0



5G NR n7 40MHz BPSK Low Channel RB216-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n7 40MHz BPSK Middle Channel RB1-0



5G NR n7 40MHz BPSK High Channel RB1-0



5G NR n7 40MHz BPSK Middle Channel RB1-215



5G NR n7 40MHz BPSK High Channel RB1-215



5G NR n7 40MHz BPSK Middle Channel RB216-0



5G NR n7 40MHz BPSK High Channel RB216-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.2. LTE BAND 12 AND 5G NR n12

LIMITS

FCC: §27.53

(g) For operations in the 600 MHz band and the 698-746 MHz band, the power of any emission outside a licensee's frequency band(s) of operation shall be attenuated below the transmitter power (P) within the licensed band(s) of operation, measured in watts, by at least 43 + 10 log (P) dB. Compliance with this provision is based on the use of measurement instrumentation employing a resolution bandwidth of 100 kilohertz or greater. However, in the 100 kilohertz bands immediately outside and adjacent to a licensee's frequency block, a resolution bandwidth of at least 30 kHz may be employed.

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE BAND 12 EMISSION MASK



LTE B12 1.4MHz QPSK Low Channel RB1-0



LTE B12 1.4MHz QPSK Middle Channel RB1-0



LTE B12 1.4MHz QPSK Low Channel RB1-5



LTE B12 1.4MHz QPSK Middle Channel RB1-5

LTE B12 1.4MHz QPSK Low Channel RB6-0

LTE B12 1.4MHz QPSK Middle Channel RB6-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 1.4MHz QPSK High Channel RB1-0



LTE B12 3MHz QPSK Low Channel RB1-0



LTE B12 1.4MHz QPSK High Channel RB1-5



LTE B12 3MHz QPSK Low Channel RB1-14



LTE B12 1.4MHz QPSK High Channel RB6-0



LTE B12 3MHz QPSK Low Channel RB15-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 3MHz QPSK Middle Channel RB1-0



LTE B12 3MHz QPSK High Channel RB1-0



LTE B12 3MHz QPSK Middle Channel RB1-14



LTE B12 3MHz QPSK High Channel RB1-14



LTE B12 3MHz QPSK Middle Channel RB15-0



LTE B12 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 5MHz QPSK Low Channel RB1-0



LTE B12 5MHz QPSK Middle Channel RB1-0



LTE B12 5MHz QPSK Low Channel RB1-24



LTE B12 5MHz QPSK Middle Channel RB1-24



LTE B12 5MHz QPSK Low Channel RB25-0



LTE B12 5MHz QPSK Middle Channel RB25-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 5MHz QPSK High Channel RB1-0



LTE B12 10MHz QPSK Low Channel RB1-0



LTE B12 5MHz QPSK High Channel RB1-24



LTE B12 10MHz QPSK Low Channel RB1-49



LTE B12 5MHz QPSK High Channel RB25-0

LTE B12 10MHz QPSK Low Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 10MHz QPSK Middle Channel RB1-0



LTE B12 10MHz QPSK High Channel RB1-0



LTE B12 10MHz QPSK Middle Channel RB1-49



LTE B12 10MHz QPSK High Channel RB1-49



LTE B12 10MHz QPSK Middle Channel RB50-0



LTE B12 10MHz QPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n12 EMISSION MASK



5G NR n12 5MHz BPSK Low Channel RB1-0, ID:32061



5G NR n12 5MHz BPSK Middle Channel RB1-0, ID:32061



5G NR n12 5MHz BPSK Low Channel RB1-24, ID:32061



5G NR n12 5MHz BPSK Middle Channel RB1-24, ID:32061



5G NR n12 5MHz BPSK Low Channel RB25-0, ID:32061



5G NR n12 5MHz BPSK Middle Channel RB25-0, ID:32061

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n12 5MHz BPSK High Channel RB1-0, ID:32061



5G NR n12 10MHz BPSK Low Channel RB1-0, ID:32061



5G NR n12 5MHz BPSK High Channel RB1-24, ID:32061



5G NR n12 10MHz BPSK Low Channel RB1-51, ID:32061



5G NR n12 5MHz BPSK High Channel RB25-0, ID:32061



5G NR n12 10MHz BPSK Low Channel RB50-0, ID:32061

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n12 10MHz BPSK Middle Channel RB1-0, ID:32061



5G NR n12 10MHz BPSK High Channel RB1-0, ID:32061



5G NR n12 10MHz BPSK Middle Channel RB1-51, ID:32061



5G NR n12 10MHz BPSK High Channel RB1-51, ID:32061



5G NR n12 10MHz BPSK Middle Channel RB50-0, ID:32061



5G NR n12 10MHz BPSK High Channel RB50-0, ID:32061

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n12 15MHz BPSK Low Channel RB1-0, ID:32061



5G NR n12 15MHz BPSK Middle Channel RB1-0, ID:32061



5G NR n12 15MHz BPSK Low Channel RB1-78, ID:32061



5G NR n12 15MHz BPSK Middle Channel RB1-78, ID:32061



5G NR n12 15MHz BPSK Low Channel RB75-0, ID:32061



5G NR n12 15MHz BPSK Middle Channel RB75-0, ID:32061

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.