2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 52-Tones, RU Index 37

STRADDLE CHANNEL ANT 6 6545



STRADDLE CHANNEL ANT 5 6545



MID CHANNEL ANT 6 6705

MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865

STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 52-Tones, RU Index 45



STRADDLE CHANNEL ANT 6 6545



STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705

MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865



STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 52-Tones, RU Index 52

STRADDLE CHANNEL ANT 6 6545

STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705

MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865

STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU Mode



STRADDLE CHANNEL ANT 6 6545



STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705



MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865



STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 52-Tones, RU Index 37

STRADDLE CHANNEL ANT 6 6545

STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705



MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865



STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 52-Tones, RU Index 45

STRADDLE CHANNEL ANT 6 6545



STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705



MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865



STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 52-Tones, RU Index 52

STRADDLE CHANNEL ANT 6 6545



STRADDLE CHANNEL ANT 5 6545

MID CHANNEL ANT 6 6705

MID CHANNEL ANT 5 6705

STRADDLE CHANNEL ANT 6 6865

STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode



STRADDLE CHANNEL ANT 6 6545

STRADDLE CHANNEL ANT 5 6545



MID CHANNEL ANT 6 6705

MID CHANNEL ANT 5 6705



STRADDLE CHANNEL ANT 6 6865

STRADDLE CHANNEL ANT 5 6865

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.12. 802.11be EHT160 MODE IN THE UNII-7 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 484-Tones, RU Index 65

MID CHANNEL 6665



STRADDLE 6825

1TX Antenna 6 MODE (FCC+IC) MOBILE – 484-Tones, RU Index S66

MID CHANNEL 6665

STRADDLE 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



MID CHANNEL 6665

STRADDLE 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 484-Tones, RU Index 65



MID CHANNEL 6665



STRADDLE 6825

1TX Antenna 5 MODE (FCC+IC) MOBILE – 26-Tones, RU IndexS66



MID CHANNEL 6665



STRADDLE 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE

MID CHANNEL 6665



STRADDLE 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 484-Tones, RU Index 65

MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665

STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 484-Tones, RU Index S66

MID CHANNEL ANT 6 6665

MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU Mode

MID CHANNEL ANT 6 6665

MID CHANNEL ANT 5 6665

STRADDLE ANT 6 6825

STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 484-Tones, RU Index 65



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 484-Tones, RU Index S66



MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665



STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

MID CHANNEL ANT 6 6665



MID CHANNEL ANT 5 6665

STRADDLE ANT 6 6825



STRADDLE ANT 5 6825

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.13. 802.11be EHT20 MODE IN THE UNII-8 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 82



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 83

LOW CHANNEL 6895



MID CHANNEL 6995

HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995

HIGH CHANNEL 7095

CHANNEL 233 - 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 82



LOW CHANNEL 6895

MID CHANNEL 6995

HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 83

LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995

HIGH CHANNEL 7095



CHANNEL 233 - 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 106 + 26-Tones, RU Index 82

LOW CHANNEL ANT 6 6895

LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995

MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095

HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 106 + 26-Tones, RU Index 83



LOW CHANNEL ANT 6 6895

LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

CHANNEL 233 - ANT 6 7115



CHANNEL 233 - ANT 5 7115

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26 -Tones, RU Index 82

LOW CHANNEL ANT 6 6895

LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995

MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095

HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26 -Tones, RU Index 83

LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995

MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

CHANNEL 233 - ANT 6 7115



CHANNEL 233 - ANT 5 7715

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.14. 802.11be EHT40 MODE IN THE UNII-8 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 82

STRADDLE CHANNEL, 6885

LOW CHANNEL 6965

HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 84

STRADDLE CHANNEL, 6885

LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 85

STRADDLE CHANNEL, 6885

LOW CHANNEL 6965

HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE

STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26 -Tones, RU Index 82

STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26 -Tones, RU Index 84

STRADDLE CHANNEL, 6885



LOW CHANNEL 6965

HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26 -Tones, RU Index 85

STRADDLE CHANNEL, 6885



LOW CHANNEL 6965

HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE

STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 106 + 26 -Tones, RU Index 82

STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885



LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 106 + 26 -Tones, RU Index 84

STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – 106 + 26 -Tones, RU Index 85

STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965



HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE (FCC + IC) – SU MODE

STRADDLE CHANNEL, Ant 6 6885

STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965

LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26 -Tones, RU Index 82

STRADDLE CHANNEL, Ant 6 6885

STRADDLE CHANNEL, Ant 5 6885



LOW CHANNEL ANT 6 6965

LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26 -Tones, RU Index 84

STRADDLE CHANNEL, Ant 6 6885

STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085

HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26 -Tones, RU Index 85



STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965

LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode



STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.