2TX Antenna 6 + Antenna 5 SDM MODE – MRU 106+26, Index 83



LOW CHANNEL, 6125 MHz [ANT 6]



LOW CHANNEL, 6125 MHz [ANT 5]

MID CHANNEL, 6245 MHz [ANT 6]

MID CHANNEL, 6245 MHz [ANT 5]

HIGH CHANNEL, 6405 MHz [ANT 6]

HIGH CHANNEL, 6405 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 106+26, Index 85



LOW CHANNEL, 6125 MHz [ANT 6]

LOW CHANNEL, 6125 MHz [ANT 5]

MID CHANNEL, 6245 MHz [ANT 6]

MID CHANNEL, 6245 MHz [ANT 5]

HIGH CHANNEL, 6405 MHz [ANT 6]

HIGH CHANNEL, 6405 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.3. 802.11be EHT80 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE – SU

LOW CHANNEL, 6145 MHz

MID CHANNEL, 6225 MHz



HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 91



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz

HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 92



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz

HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 93



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz



HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – SU

LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz

HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 91



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz



HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 92



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz



HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 93



LOW CHANNEL, 6145 MHz



MID CHANNEL, 6225 MHz



HIGH CHANNEL, 6385 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – SU

LOW CHANNEL, 6145 MHz [ANT 6]



LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]

HIGH CHANNEL, 6385 MHz [ANT 6]

HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 484+242, Index 91

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]

HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 484+242, Index 92

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]



HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 484+242, Index 93

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]



HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – SU

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]

HIGH CHANNEL, 6385 MHz [ANT 6]

HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 484+242, Index 91

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]



HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 484+242, Index 92

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]



HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 484+242, Index 93

LOW CHANNEL, 6145 MHz [ANT 6]

LOW CHANNEL, 6145 MHz [ANT 5]

MID CHANNEL, 6225 MHz [ANT 6]

MID CHANNEL, 6225 MHz [ANT 5]



HIGH CHANNEL, 6385 MHz [ANT 6]



HIGH CHANNEL, 6385 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.4. 802.11be EHT160 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE – SU

LOW CHANNEL, 6185 MHz



HIGH CHANNEL, 6345 MHz

1TX Antenna 6 MODE – MRU 484+242, Index 91

LOW CHANNEL, 6185 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL, 6345 MHz

1TX Antenna 6 MODE – MRU 484+242, Index 92



LOW CHANNEL, 6185 MHz



HIGH CHANNEL, 6345 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index S92



LOW CHANNEL, 6185 MHz

HIGH CHANNEL, 6345 MHz

1TX Antenna 5 MODE – SU



LOW CHANNEL, 6185 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL, 6345 MHz

1TX Antenna 5 MODE – MRU 484+242, Index 91



LOW CHANNEL, 6185 MHz



HIGH CHANNEL, 6345 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 92



LOW CHANNEL, 6185 MHz



HIGH CHANNEL, 6345 MHz

1TX Antenna 5 MODE – MRU 484+242, Index S92



LOW CHANNEL, 6185 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL, 6345 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.