

LTE B71 5MHz QPSK High Channel RB1-0



LTE B71 10MHz QPSK Low Channel RB1-0



LTE B71 5MHz QPSK High Channel RB1-24



LTE B71 10MHz QPSK Low Channel RB1-49



LTE B71 5MHz QPSK High Channel RB25-0



LTE B71 10MHz QPSK Low Channel RB50-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 10MHz QPSK Middle Channel RB1-0



LTE B71 10MHz QPSK High Channel RB1-0



LTE B71 10MHz QPSK Middle Channel RB1-49



LTE B71 10MHz QPSK High Channel RB1-49



LTE B71 10MHz QPSK Middle Channel RB50-0



LTE B71 10MHz QPSK High Channel RB50-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 15MHz QPSK Low Channel RB1-0



LTE B71 15MHz QPSK Middle Channel RB1-0



LTE B71 15MHz QPSK Low Channel RB1-74



LTE B71 15MHz QPSK Middle Channel RB1-74



LTE B71 15MHz QPSK Low Channel RB75-0



LTE B71 15MHz QPSK Middle Channel RB75-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 15MHz QPSK High Channel RB1-0



LTE B71 20MHz QPSK Low Channel RB1-0



LTE B71 15MHz QPSK High Channel RB1-74



LTE B71 20MHz QPSK Low Channel RB1-99



LTE B71 15MHz QPSK High Channel RB75-0



LTE B71 20MHz QPSK Low Channel RB100-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B71 20MHz QPSK Middle Channel RB1-0



LTE B71 20MHz QPSK High Channel RB1-0



LTE B71 20MHz QPSK Middle Channel RB1-99



LTE B71 20MHz QPSK High Channel RB1-99



LTE B71 20MHz QPSK Middle Channel RB100-0



LTE B71 20MHz QPSK High Channel RB100-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n71 EMISSION MASK



5G NR n71 5MHz BPSK Low Channel RB1-0



5G NR n71 5MHz BPSK Middle Channel RB1-0



5G NR n71 5MHz BPSK Low Channel RB1-24



5G NR n71 5MHz BPSK Middle Channel RB1-24



5G NR n71 5MHz BPSK Low Channel RB25-0



5G NR n71 5MHz BPSK Middle Channel RB25-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n71 5MHz BPSK High Channel RB1-0



5G NR n71 10MHz BPSK Low Channel RB1-0



5G NR n71 5MHz BPSK High Channel RB1-24



5G NR n71 10MHz BPSK Low Channel RB1-51



5G NR n71 5MHz BPSK High Channel RB25-0



5G NR n71 10MHz BPSK Low Channel RB50-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n71 10MHz BPSK Middle Channel RB1-0



5G NR n71 10MHz BPSK High Channel RB1-0



5G NR n71 10MHz BPSK Middle Channel RB1-51



5G NR n71 10MHz BPSK High Channel RB1-51



5G NR n71 10MHz BPSK Middle Channel RB50-0



5G NR n71 10MHz BPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n71 15MHz BPSK Low Channel RB1-0



5G NR n71 15MHz BPSK Middle Channel RB1-0



5G NR n71 15MHz BPSK Low Channel RB1-78



5G NR n71 15MHz BPSK Middle Channel RB1-78



5G NR n71 15MHz BPSK Low Channel RB75-0

5G NR n71 15MHz BPSK Middle Channel RB75-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n71 15MHz BPSK High Channel RB1-0



5G NR n71 20MHz BPSK Low Channel RB1-0



5G NR n71 15MHz BPSK High Channel RB1-78



5G NR n71 20MHz BPSK Low Channel RB1-105



5G NR n71 15MHz BPSK High Channel RB75-0



5G NR n71 20MHz BPSK Low Channel RB100-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n71 20MHz BPSK Middle Channel RB1-0



5G NR n71 20MHz BPSK High Channel RB1-0



5G NR n71 20MHz BPSK Middle Channel RB1-105



5G NR n71 20MHz BPSK High Channel RB1-105



5G NR n71 20MHz BPSK Middle Channel RB100-0



5G NR n71 20MHz BPSK High Channel RB100-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.14. 5G NR n77 (FCC Part 27 3450-3550MHz)

LIMITS

FCC: §27.53
(n) 3.45 GHz Service. The following emission limits apply to stations transmitting in the 3450-3550 MHz band:
(2) For mobile operations in the 3450-3550 MHz band, the conducted power of any emission outside the licensee's authorized bandwidth shall not exceed −13 dBm/MHz. Compliance with this paragraph (n)(2) is based on the use of measurement instrumentation employing a resolution bandwidth of 1 megahertz or greater. However, in the 1 megahertz bands immediately outside and adjacent to the licensee's frequency block, a resolution bandwidth of at least one percent of the emission bandwidth of the fundamental emission of the transmitter may be employed, but limited to a maximum of 200 kHz. In the bands between 1 and 5 MHz removed from the licensee's frequency block, the minimum resolution bandwidth for the measurement shall be 500 kHz. The emission bandwidth is defined as the width of the signal between two points, one below the carrier center frequency and one above the carrier center frequency, outside of which all emissions are attenuated at least 26 dB below the transmitter power.

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK Low Channel RB1-0



5G NR n77 10MHz BPSK Middle Channel RB1-0



5G NR n77 10MHz BPSK Low Channel RB1-23



5G NR n77 10MHz BPSK Middle Channel RB1-23



5G NR n77 10MHz BPSK Low Channel RB24-0



5G NR n77 10MHz BPSK Middle Channel RB24-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK High Channel RB1-0



5G NR n77 15MHz BPSK Low Channel RB1-0



5G NR n77 10MHz BPSK High Channel RB1-23



5G NR n77 15MHz BPSK Low Channel RB1-37



5G NR n77 10MHz BPSK High Channel RB24-0



5G NR n77 15MHz BPSK Low Channel RB36-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n77 15MHz BPSK Middle Channel RB1-0



5G NR n77 15MHz BPSK High Channel RB1-0



5G NR n77 15MHz BPSK Middle Channel RB1-37



5G NR n77 15MHz BPSK High Channel RB1-37

5G NR n77 15MHz BPSK Middle Channel RB36-0



5G NR n77 15MHz BPSK High Channel RB36-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB1-0



5G NR n77 20MHz BPSK Middle Channel RB1-0



5G NR n77 20MHz BPSK Low Channel RB1-50



5G NR n77 20MHz BPSK Middle Channel RB1-50



5G NR n77 20MHz BPSK Low Channel RB50-0



5G NR n77 20MHz BPSK Middle Channel RB50-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK High Channel RB1-0



5G NR n77 30MHz BPSK Low Channel RB1-0



5G NR n77 20MHz BPSK High Channel RB1-50



5G NR n77 30MHz BPSK Low Channel RB1-77



5G NR n77 20MHz BPSK High Channel RB50-0



5G NR n77 30MHz BPSK Low Channel RB75-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 30MHz BPSK Middle Channel RB1-0



5G NR n77 30MHz BPSK High Channel RB1-0



5G NR n77 30MHz BPSK Middle Channel RB1-77



5G NR n77 30MHz BPSK High Channel RB1-77



5G NR n77 30MHz BPSK Middle Channel RB75-0



5G NR n77 30MHz BPSK High Channel RB75-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 40MHz BPSK Low Channel RB1-0



5G NR n77 40MHz BPSK Middle Channel RB1-0



5G NR n77 40MHz BPSK Low Channel RB1-105



5G NR n77 40MHz BPSK Middle Channel RB1-105



5G NR n77 40MHz BPSK Low Channel RB100-0

5G NR n77 40MHz BPSK Middle Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 40MHz BPSK High Channel RB1-0



5G NR n77 50MHz BPSK Low Channel RB1-0



5G NR n77 40MHz BPSK High Channel RB1-105



5G NR n77 50MHz BPSK Low Channel RB1-132



5G NR n77 40MHz BPSK High Channel RB100-0

5G NR n77 50MHz BPSK Low Channel RB128-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 50MHz BPSK Middle Channel RB1-0



5G NR n77 50MHz BPSK High Channel RB1-0



5G NR n77 50MHz BPSK Middle Channel RB1-132



5G NR n77 50MHz BPSK High Channel RB1-132

5G NR n77 50MHz BPSK Middle Channel RB128-0



5G NR n77 50MHz BPSK High Channel RB128-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 60MHz BPSK Low Channel RB1-0



5G NR n77 60MHz BPSK Middle Channel RB1-0



5G NR n77 60MHz BPSK Low Channel RB1-161



5G NR n77 60MHz BPSK Middle Channel RB1-161



5G NR n77 60MHz BPSK Low Channel RB162-0



5G NR n77 60MHz BPSK Middle Channel RB162-0

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.