2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode



LOW CHANNEL ANT 6 5965

LOW CHANNEL ANT 5 5965



MID CHANNEL ANT 6 6165

MID CHANNEL ANT 5 6165

HIGH CHANNEL ANT 6 6405

HIGH CHANNEL ANT 5 6405

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.3. 802.11be EHT80 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 61

LOW CHANNEL 5985

MID CHANNEL 6145

HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 62



MID CHANNEL 6145

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 64



LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 5985



MID CHANNEL 6145

HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 61

LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 62

MID CHANNEL 6145

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 64



LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 61

LOW CHANNEL ANT 6 5985

LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145

MID CHANNEL ANT 5 6145

HIGH CHANNEL ANT 6 6385

HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 62



MID CHANNEL ANT 6 6145

MID CHANNEL ANT 5 6145

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 64

LOW CHANNEL ANT 6 5985

LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145

MID CHANNEL ANT 5 6145

HIGH CHANNEL ANT 6 6385

HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 5985

LOW CHANNEL ANT 5 5985

MID CHANNEL ANT 6 6145

MID CHANNEL ANT 5 6145

HIGH CHANNEL ANT 6 6385

HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 61



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 62

MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 64



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 6145



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.4. 802.11be EHT160 MODE IN THE UNII-5 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53

LOW CHANNEL 6025

MID CHANNEL 6185

HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index S60



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 6025



MID CHANNEL 6185

HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53

LOW CHANNEL 6025



MID CHANNEL 6185

HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index S60

LOW CHANNEL 6025

MID CHANNEL 6185

HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 6025



MID CHANNEL 6185

HIGH CHANNEL 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106-Tones, RU Index 53

LOW CHANNEL ANT 6 6025

LOW CHANNEL ANT 5 6025

MID CHANNEL ANT 6 6185

MID CHANNEL ANT 5 6185

HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106-Tones, RU Index S60



LOW CHANNEL ANT 6 6025

LOW CHANNEL ANT 5 6025

MID CHANNEL ANT 6 6185

MID CHANNEL ANT 5 6185

HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6025

LOW CHANNEL ANT 5 6025

MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 53

LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025

MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index S60

LOW CHANNEL ANT 6 6025

LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185

MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025

MID CHANNEL ANT 6 6185

MID CHANNEL ANT 5 6185

HIGH CHANNEL ANT 6 6345

HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.5. 802.11be EHT20 MODE IN THE UNII-6 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 82

LOW CHANNEL 6435

MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 83

LOW CHANNEL 6435

MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 6435

MID CHANNEL 6475



HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 82

LOW CHANNEL 6435

MID CHANNEL 6475

HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106 + 26-Tones, RU Index 83

LOW CHANNEL 6435

MID CHANNEL 6475

HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 6435

MID CHANNEL 6475

HIGH CHANNEL 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106 + 26-Tones, RU Index 82

LOW CHANNEL ANT 6 6435

LOW CHANNEL ANT 5 6435

MID CHANNEL ANT 6 6475

MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106 + 26-Tones, RU Index 83

LOW CHANNEL ANT 6 6435

LOW CHANNEL ANT 5 6435

MID CHANNEL ANT 6 6475



MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515



HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6435



LOW CHANNEL ANT 5 6435



MID CHANNEL ANT 6 6475

MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515

HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26-Tones, RU Index 82

LOW CHANNEL ANT 6 6435

LOW CHANNEL ANT 5 6435

MID CHANNEL ANT 6 6475

MID CHANNEL ANT 5 6475

HIGH CHANNEL ANT 6 6515

HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106 + 26-Tones, RU Index 83

LOW CHANNEL ANT 6 6435

LOW CHANNEL ANT 5 6435

MID CHANNEL ANT 6 6475

MID CHANNEL ANT 5 6475

HIGH CHANNEL ANT 6 6515

HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode



LOW CHANNEL ANT 6 6435

LOW CHANNEL ANT 5 6435

MID CHANNEL ANT 6 6475

MID CHANNEL ANT 5 6475



HIGH CHANNEL ANT 6 6515

HIGH CHANNEL ANT 5 6515

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.6. 802.11be EHT40 MODE IN THE UNII-6 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



LOW CHANNEL 6445

MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



LOW CHANNEL 6445

MID CHANNEL 6485

STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56

LOW CHANNEL 6445

MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6445

MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53

LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54

LOW CHANNEL 6445



MID CHANNEL 6485



STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56

LOW CHANNEL 6445

MID CHANNEL 6485

STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6445

MID CHANNEL 6485

STRADDLE CHANNEL 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106-Tones, RU Index 53



LOW CHANNEL ANT 6 6445

LOW CHANNEL ANT 5 6445



MID CHANNEL ANT 6 6485

MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106-Tones, RU Index 54



LOW CHANNEL ANT 6 6445

LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 106-Tones, RU Index 56

LOW CHANNEL ANT 6 6445

LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525



STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – SU Mode



LOW CHANNEL ANT 6 6445



LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485

MID CHANNEL ANT 5 6485

STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 53

LOW CHANNEL ANT 6 6445

LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485

MID CHANNEL ANT 5 6485



STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 54

LOW CHANNEL ANT 6 6445

LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485

STRADDLE CHANNEL ANT 6 6525



STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 56

LOW CHANNEL ANT 6 6445



LOW CHANNEL ANT 5 6445



MID CHANNEL ANT 6 6485

MID CHANNEL ANT 5 6485

STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6445



LOW CHANNEL ANT 5 6445

MID CHANNEL ANT 6 6485



MID CHANNEL ANT 5 6485

STRADDLE CHANNEL ANT 6 6525

STRADDLE CHANNEL ANT 5 6525

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.6.7. 802.11be EHT80 MODE IN THE UNII-6 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 61



LOW CHANNEL 6465

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 62



LOW CHANNEL 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 64



LOW CHANNEL 6465

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE

LOW CHANNEL 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 61



LOW CHANNEL 6465

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 62



LOW CHANNEL 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 242-Tones, RU Index 64



LOW CHANNEL 6465

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 61

LOW CHANNEL ANT 6 6465



LOW CHANNEL ANT 5 6465

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 62

LOW CHANNEL ANT 6 6465



LOW CHANNEL ANT 5 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – 242-Tones, RU Index 64

LOW CHANNEL ANT 6 6465



LOW CHANNEL ANT 5 6465

2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6465

LOW CHANNEL ANT 5 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 61

LOW CHANNEL ANT 6 6465

LOW CHANNEL ANT 5 6465

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 62



LOW CHANNEL ANT 6 6465

LOW CHANNEL ANT 5 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 242-Tones, RU Index 64



LOW CHANNEL ANT 6 6465

LOW CHANNEL ANT 5 6465

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode

LOW CHANNEL ANT 6 6465

LOW CHANNEL ANT 5 6465

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.