LTE B48 10MHz QPSK High Channel RB1-0

LTE B48 15MHz QPSK Low Channel RB1-0

LTE B48 10MHz QPSK High Channel RB1-49

LTE B48 15MHz QPSK Low Channel RB1-74




LTE B48 10MHz QPSK High Channel RB50-0

LTE B48 15MHz QPSK Low Channel RB75-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

LTE B48 15MHz QPSK Middle ChannelRB1-0 (3617.5MHz)

LTE B48 15MHz QPSK Middle ChannelRB1-0 (3622.5MHz)

LTE B48 15MHz QPSK Middle ChannelRB1-74 (3617.5MHz)

LTE B48 15MHz QPSK Middle ChannelRB1-74 (3622.5MHz)

LTE B48 15MHz QPSK Middle ChannelRB75-0 (3617.5MHz)

LTE B48 15MHz QPSK Middle ChannelRB75-0 (3622.5MHz)



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

LTE B48 15MHz QPSK High Channel RB1-0




LTE B48 20MHz QPSK Low Channel RB1-0

LTE B48 15MHz QPSK High Channel RB1-74

LTE B48 20MHz QPSK Low Channel RB1-99




LTE B48 15MHz QPSK High Channel RB75-0

LTE B48 20MHz QPSK Low Channel RB100-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

LTE B48 20MHz QPSK Middle ChannelRB1-0

LTE B48 20MHz QPSK High Channel RB1-0

LTE B48 20MHz QPSK Middle ChannelRB1-99

LTE B48 20MHz QPSK High Channel RB1-99




LTE B48 20MHz QPSK Middle ChannelRB100-0

LTE B48 20MHz QPSK High Channel RB100-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 9.2.3. 5G NR n48 SISO EMISSION MASK




5G NR n48 10MHz BPSK Low Channel RB1-0




5G NR n48 10MHz BPSK Middle Channel RB1-0




5G NR n48 10MHz BPSK Low Channel RB1-23




5G NR n48 10MHz BPSK Middle Channel RB1-23




5G NR n48 10MHz BPSK Low Channel RB24-0




5G NR n48 10MHz BPSK Middle Channel RB24-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 10MHz BPSK High Channel RB1-0




5G NR n48 15MHz BPSK Low Channel RB1-0




5G NR n48 10MHz BPSK High Channel RB1-23




5G NR n48 15MHz BPSK Low Channel RB1-37




5G NR n48 10MHz BPSK High Channel RB24-0




5G NR n48 15MHz BPSK Low Channel RB36-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 15MHz BPSK Middle Channel RB1-0 (3617.5MHz)




5G NR n48 15MHz BPSK Middle Channel RB1-0 (3622.5MHz)




5G NR n48 15MHz BPSK Middle Channel RB1-37 (3617.5MHz)




5G NR n48 15MHz BPSK Middle Channel RB1-37 (3622.5MHz)




5G NR n48 15MHz BPSK Middle Channel RB36-0 (3617.5MHz)




5G NR n48 15MHz BPSK Middle Channel RB36-0 (3622.5MHz)



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 15MHz BPSK High Channel RB1-0




5G NR n48 20MHz BPSK Low Channel RB1-0




5G NR n48 15MHz BPSK High Channel RB1-37




5G NR n48 20MHz BPSK Low Channel RB1-50




5G NR n48 15MHz BPSK High Channel RB36-0




5G NR n48 20MHz BPSK Low Channel RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 20MHz BPSK Middle Channel RB1-0




5G NR n48 20MHz BPSK High Channel RB1-0




5G NR n48 20MHz BPSK Middle Channel RB1-50




5G NR n48 20MHz BPSK High Channel RB1-50




5G NR n48 20MHz BPSK Middle Channel RB50-0




5G NR n48 20MHz BPSK High Channel RB50-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 30MHz BPSK Low Channel RB1-0




5G NR n48 30MHz BPSK Middle Channel RB1-0




5G NR n48 30MHz BPSK Low Channel RB1-77




5G NR n48 30MHz BPSK Middle Channel RB1-77




5G NR n48 30MHz BPSK Low Channel RB75-0




5G NR n48 30MHz BPSK Middle Channel RB75-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 30MHz BPSK High Channel RB1-0




5G NR n48 40MHz BPSK Low Channel RB1-0




5G NR n48 30MHz BPSK High Channel RB1-77




5G NR n48 40MHz BPSK Low Channel RB1-105




5G NR n48 30MHz BPSK High Channel RB75-0




5G NR n48 40MHz BPSK Low Channel RB100-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n48 40MHz BPSK Middle Channel RB1-0




5G NR n48 40MHz BPSK High Channel RB1-0




5G NR n48 40MHz BPSK Middle Channel RB1-105




5G NR n48 40MHz BPSK High Channel RB1-105




5G NR n48 40MHz BPSK Middle Channel RB100-0




5G NR n48 40MHz BPSK High Channel RB100-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 9.2.4. 5G NR n48 SISO ADJACENT CHANNEL POWER

5G NR N48 10MHz BPSK Low Channel RB1-0




5G NR N48 10MHz BPSK Middle Channel RB1-0




5G NR N48 10MHz BPSK Low Channel RB1-23




5G NR N48 10MHz BPSK Middle Channel RB1-23

5G NR N48 10MHz BPSK Low Channel RB24-0




5G NR N48 10MHz BPSK Middle Channel RB24-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR N48 10MHz BPSK High Channel RB1-0




5G NR N48 15MHz BPSK Low Channel RB1-0




5G NR N48 10MHz BPSK High Channel RB1-23




5G NR N48 15MHz BPSK Low Channel RB1-37




5G NR N48 10MHz BPSK High Channel RB24-0

5G NR N48 15MHz BPSK Low Channel RB36-0



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*