



Date: July 14th, 2025

Federal Communications Commission
Equipment Authorization Branch
7435 Oakland Mills Rd.
Columbia MD 21046d

Attn: OET Department

To whom it may concern:

We, Apple Inc., attest that these devices under **FCC ID:**

Model(s)	FCC ID
A3472	BCG-E9186A
A3713	BCG-E9192A
A3714	BCG-E9193A
A3715	BCG-E9194A
A3473	BCG-E9187A
A3716	BCG-E9195A
A3717	BCG-E9196A
A3718	BCG-E9197A
A3447	BCG-E9188A
A3719	BCG-E9198A
A3720	BCG-E9203A
A3721	BCG-E9204A

In the case of 6GHz band, this device may puncture a channel for network optimization purposes but not to avoid licensed incumbent. If a licensed incumbent is detected, the device may do bandwidth reduction or completely move the channel. If the device does channel puncturing in order to optimize network performance, the device continues using CBP on the punctured regions.

Sincerely,

Abhishek Rala
Apple Inc.
Global Certification Manager
arala@apple.com