

LTE B48 10MHz QPSK Low Channel RB1-0



LTE B48 10MHz QPSK Middle Channel RB1-0



LTE B48 10MHz QPSK Low Channel RB1-49



LTE B48 10MHz QPSK Middle Channel RB1-49



LTE B48 10MHz QPSK Low Channel RB50-0



LTE B48 10MHz QPSK Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE B48 10MHz QPSK High Channel RB1-0



LTE B48 15MHz QPSK Low Channel RB1-0



LTE B48 10MHz QPSK High Channel RB1-49



LTE B48 15MHz QPSK Low Channel RB1-74



LTE B48 10MHz QPSK High Channel RB50-0



LTE B48 15MHz QPSK Low Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE B48 15MHz QPSK Middle Channel RB1-0 (3617.5MHz)



LTE B48 15MHz QPSK Middle Channel RB1-0 (3622.5MHz)



LTE B48 15MHz QPSK Middle Channel RB1-74 (3617.5MHz)

LTE B48 15MHz QPSK Middle Channel RB1-0 (3622.5MHz)



LTE B48 15MHz QPSK Middle Channel RB75-0 (3617.5MHz)



LTE B48 15MHz QPSK Middle Channel RB75-0 (3622.5MHz)

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 15MHz QPSK High Channel RB1-0



LTE B48 20MHz QPSK Low Channel RB1-0



LTE B48 15MHz QPSK High Channel RB1-74



LTE B48 20MHz QPSK Low Channel RB1-99



LTE B48 15MHz QPSK High Channel RB75-0



LTE B48 20MHz QPSK Low Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 20MHz QPSK Middle Channel RB1-0



LTE B48 20MHz QPSK High Channel RB1-0



LTE B48 20MHz QPSK Middle Channel RB1-99



LTE B48 20MHz QPSK High Channel RB1-99



LTE B48 20MHz QPSK Middle Channel RB100-0



LTE B48 20MHz QPSK High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.3. 5G NR n48 SISO EMISSION MASK



5G NR n48 10MHz BPSK Low Channel RB1-0



5G NR n48 10MHz BPSK Middle Channel RB1-0



5G NR n48 10MHz BPSK Low Channel RB1-23



5G NR n48 10MHz BPSK Middle Channel RB1-23



5G NR n48 10MHz BPSK Low Channel RB24-0



5G NR n48 10MHz BPSK Middle Channel RB24-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 10MHz BPSK High Channel RB1-0



5G NR n48 15MHz BPSK Low Channel RB1-0



5G NR n48 10MHz BPSK High Channel RB1-23



5G NR n48 15MHz BPSK Low Channel RB1-37



5G NR n48 10MHz BPSK High Channel RB24-0



5G NR n48 15MHz BPSK Low Channel RB36-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz BPSK Middle Channel RB1-0 (3617.5MHz)



5G NR n48 15MHz BPSK Middle Channel RB1-0 (3622.5MHz)



5G NR n48 15MHz BPSK Middle Channel RB1-37 (3617.5MHz)



5G NR n48 15MHz BPSK Middle Channel RB1-37 (3622.5MHz)



5G NR n48 15MHz BPSK Middle Channel RB36-0 (3617.5MHz)



5G NR n48 15MHz BPSK Middle Channel RB36-0 (3622.5MHz)

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz BPSK High Channel RB1-0



5G NR n48 20MHz BPSK Low Channel RB1-0



5G NR n48 15MHz BPSK High Channel RB1-37



5G NR n48 20MHz BPSK Low Channel RB1-50



5G NR n48 15MHz BPSK High Channel RB36-0



5G NR n48 20MHz BPSK Low Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 20MHz BPSK Middle Channel RB1-0



5G NR n48 20MHz BPSK High Channel RB1-0



5G NR n48 20MHz BPSK Middle Channel RB1-50



5G NR n48 20MHz BPSK High Channel RB1-50



5G NR n48 20MHz BPSK Middle Channel RB50-0



5G NR n48 20MHz BPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 30MHz BPSK Low Channel RB1-0



5G NR n48 30MHz BPSK Middle Channel RB1-0



5G NR n48 30MHz BPSK Low Channel RB1-77



5G NR n48 30MHz BPSK Middle Channel RB1-77



5G NR n48 30MHz BPSK Low Channel RB75-0



5G NR n48 30MHz BPSK Middle Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 30MHz BPSK High Channel RB1-0



5G NR n48 40MHz BPSK Low Channel RB1-0



5G NR n48 30MHz BPSK High Channel RB1-77



5G NR n48 40MHz BPSK Low Channel RB1-105



5G NR n48 30MHz BPSK High Channel RB75-0



5G NR n48 40MHz BPSK Low Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 40MHz BPSK Middle Channel RB1-0



5G NR n48 40MHz BPSK High Channel RB1-0



5G NR n48 40MHz BPSK Middle Channel RB1-105



5G NR n48 40MHz BPSK High Channel RB1-105



5G NR n48 40MHz BPSK Middle Channel RB100-0



5G NR n48 40MHz BPSK High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.