



December 13, 2001

Grace Lin  
Intertek Testing Services  
ETL SEMKO  
1950 Evergreen Blvd., Suite 100  
Duluth, GA 30096

Phone: 678-775-2400

Dear Ms Lin:

Identified below are the differences between the Lifeline Systems Model SL318/CL320 and the SL/CL324:

- 1) a new microprocessor is used.
- 2) power is applied to the microprocessor through a new trace.
- 3) the microprocessor clock is changed to a different circuit.
- 4) control connections to the microprocessor are modified.
- 5) two component values in the RF circuit, not affecting output power or frequency, are changed.

Please feel free to use this information for FCC submittal.

Sincerely,

**SIGNED**

Clyde Dottin  
Manager, Engineering Services  
Lifeline Systems

Lifeline Systems  
111 Lawrence Street  
Framingham, MA  
01702-8156  
Phone: 508-988-1000  
Fax: 508-988-1384  
[www.lifelinesys.com](http://www.lifelinesys.com)