



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 20, 2005

RE: LG Electronics USA

FCC ID: BEJ42PX3DVUD

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The RBG connector/interface can not be found in the schematics. It appears that maybe the schematics provide are incomplete. Please review or kindly point to where this interface is found in the schematics.
- 2) FYI....This application only covered the PC peripheral portion of the device. Please note that the manufacturer is still responsible for making sure that the technical requirements for TV receivers have been verified per the FCC rules (these may be found in Sections 15.31(n), 15.107, 109, 111, 117, 118, 119,120, and 122 as applicable).

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.