From: Audix(敦吉)tina_huang
To: ted@atcb.com; major_chen; Richard Fabina;
cc: 鄭又銘; EM 張本成;
Subject: Fw: www.AmericanTCB.com ATCB005848 | BEJ9QK-W93-R | | | BEJ9QK-W93-R_ATCB005848
Date: Friday, January 25, 2008 2:17:57 AM
Attachments: LG Electronics 3RT.pdf

Dear Rich:

About your question, our answers is following:

1. The CB has noticed that page 6 of the user manual contains instructions for the user to attach a ferrite bead to each speaker wire pair near the Wireless Speaker Receiver. Are these ferrites necessary to meet the FCC limits on EMC? (They are not shown in the test setup diagram in the submitted test report.).

Answer: We have checked that does not affect FCC compliance,
The ferrites are for CE's EMI not for FCC 15 C applied .

.

Thank you!!

----- Original Message -----
From: Ted Chao
To: ben_cheng@ttemc.com.tw
Cc: 'Ted Chao' ; 'Major Chen'
Sent: Friday, January 25, 2008 1:27 PM
Subject: FW: www.AmericanTCB.com ATCB005848 | BEJ9QK-W93-R | | | BEJ9QK-W93-R_ATCB005848

From: Ted Chao [mailto:ted@atcb.com]
Sent: Friday, January 25, 2008 1:15 PM
To: ben_cheng@audixtech.com
Cc: 'Ted Chao'; 'Major Chen'
Subject: FW: www.AmericanTCB.com ATCB005848 | BEJ9QK-W93-R | | | BEJ9QK-W93-R_ATCB005848

Resent and please give a Major call.

Best

Ted

From: Richard Fabina [mailto:rfabina@atcb.com]
Sent: Friday, January 25, 2008 12:43 PM
To: ben_cheng@audixtech.com; emc@audixtech.com; monica_chang@audixtech.com
Cc: customerservice@atcb.com
Subject: www.AmericanTCB.com ATCB005848 | BEJ9QK-W93-R | | | BEJ9QK-W93-R_ATCB005848

Regarding www.AmericanTCB.com application:
ATCB ID: ATCB005848
FCC ID: BEJ9QK-W93-R
IC:
TCF:
Account name: AudixEM

The attached contains a request for additional information on the above referenced application.

I am proceeding with the grant of Certification for ATCB005847/FCC ID: BEJ9QK-W93-T.

Rich Fabina
Examining Engineer
ATCB
6731 Whittier Avenue, Suite C110
McLean, VA 22101

email: rfabina@atcb.com
alternate email: rfabina@gmail.com
USA direct number: 703-635-2881
USA corporate number: 703-847-4700
USA corporate fax: 703-847-6888