

Request for Class II Permissive Change

FCC ID: BEJE2242TA

Data: Jun 20, 2012

Please be notified that we, the undersigned, LG Electronics U.S.A., Inc. declare that the reasons for this Class II permissive change are as below:

1. To change the PCB of main board

Thank you.

Sincerely,



Christopher Johnson/ Sr. Manager





LG Electronics U.S.A., Inc.

Tel: 02-3777-1114

Fax: 02-6719-7509

1000 Sylvan Avenue, Englewood Cliffs, NJ 07632,
United States
Tel: 02-3777-1114
Fax: 02-6719-7509

PCB and block compare

Maker	old	new	Change
PCB Photo			Different: 1. Main IC circuit 2. LED drive
Block			Same : 1)Crystal :same 2) Resolution: same 3)Panel :same 4)Adapter : same





1000 Sylvan Avenue, Englewood Cliffs, NJ 07632,
United States
Tel: 02-3777-1114
Fax: 02-6719-7509

Circuit diagram compare-1

Maker	old	new	Change
Main IC circuit			1) Size: different 2) Pin No.: Same 3) Pin output: change 4) Maker different
LVDS out			Same

1000 Sylvan Avenue, Englewood Cliffs, NJ 07632,
United States
Tel: 02-3777-1114
Fax: 02-6719-7509

Circuit diagram compare-2

Maker	old	new	Change
LED drive CH			Change : Mos transistor →resistor Reason: cost down
19V to 5V			Same

1000 Sylvan Avenue, Englewood Cliffs, NJ 07632,
United States
Tel: 02-3777-1114
Fax: 02-6719-7509

Circuit diagram compare-3

Maker	old	new	Change
Dsub Input			Same
Control PCB			Same
2M flash			Same