



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 25, 2006

RE: FCC ID: BEJKG220_ATCB003130
Attention: Jay Kim

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the operational description appears to be more of a trouble shooting guide. Please provide an operational description of the device.
2. Please provide the tune up procedure for the device.
3. Please note that the summary of tests states this is part 22, however, the test data is part 24. Please correct.
4. Please note that only the end result is provided for EIRP values of the fundamental. How was this value determined (i.e. what was the signal generator drive level, what was the gain value of the substitution antenna etc)? Please provide the factors used to determine EIRP on page 6 of the report.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.