

Tim,

Please see the reply for the comments as following.

1. This phone is for India. That's why the DC adapter is India type.
2. 3. This phone support IS95 and IS2000. It does not support CDMA2000.
4. This phone does not support USB cable. Please see updated Manual(Uploaded).
5. We uploaded modified manual
6. We uploaded modified manual
7. We uploaded modified SAR Report
8. We uploaded modified SAR Report.
9. This phone does not support connection for headset. There are no port for headset.

If you have any questions, please let me know.

Thank you.

Jay Kim.