



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 22, 2005

RE: FCC ID: BEJM4300_ATCB002795
Attention: Jay Kim

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the conducted power levels between the EMC and SAR report must be within 0.5dB. Please note that the difference in the current reports is greater than 1dB. Please explain and please provide test data showing the power levels within the allowed variance.
2. Please explain the z axis plot on page 45 of the SAR report. The plot does not appear to be as expected according to IEEE 1528 and OET 65C. The plot seems to indicate that there is a problem with the SAR measurement or measurement system.
3. Please note that further question may arise based on the answers to the above items.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.