



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 15, 2006

RE: FCC ID: BEJMG810_ATCB003269
Attention: Jay Kim

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the BT only has to be operating in the worse case configuration. Once the worse case without the BT operating has been found it is only necessary to turn the BT on for that configuration and take additional data for that configuration. Please note that the SAR report says "Bluetooth function enable" or "Bluetooth function enable, disable and GPRS". To which of the entries in the tables is the note referring? Please explain.
2. On page 22 of the SAR report you state "Head, Bluetooth function enable and disable". This would indicate that both conditions (BT on and BT off) were tested. However, there is no indication in the table as to which test configuration has the BT on and which has the BT off. Please explain.
- 3.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.