



January 18, 2018

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046 USA

RE: FCC ID: BEJNM4HO (CONFIDENTIAL)

To Whom It May Concern:

We are kindly requesting to place the aforementioned application into Audit Mode so that we may update the DXX (RFID) test report. Upon selling this device to a customer, the manufacturer/grantee noted that the Frequency Stability section of this report shows a DC voltage of 12V, however, this should show 5V. We confirm that the testing was performed at 5Vdc and that the 12V shown in the report is a typo.

Thank you for your attention to this matter.

Best Regards,

Steven Yoon
Steven.yoon@pctest.com