


AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5180MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5200MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5240MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5260MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5300MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5320MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5500MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5600MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/17	Temp./Hum.	25°C /55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5700MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/18	Temp./Hum.	25°C /55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5720MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/18	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5745MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303


Test Date	2016/11/18	Temp./Hum.	25℃/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5785MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/18	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5825MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25℃/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5190MHz
		Test Voltage	AC 120V, 60Hz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25℃/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5230MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25℃/55%
Mode	802.11n-HT40	UNII Band	II-2A
		Frequency	TX 5270MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
		Frequency	TX 5310MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25℃/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5510MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/11/21	Temp./Hum.	25°C /55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5590MHz
		Test Voltage	AC 120V, 60HZ
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Note: The results have been included cable loss and antenna gain.

AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Note: The results have been included cable loss and antenna gain.